

CITY OF SULTAN

Americans With Disabilities Act (ADA) Access Plan for the Public Right-of-Way



APPENDIX B1

GIS Curb Ramp Inventory and Prioritization

DRAFT July 2023

Prepared by



City of Sultan
2023 ADA Access Plan GIS Curb Ramp Inventory

| TSI_Curb_Ramp_ID | OBJECTID * | SHAPE * | Condition * | Ramp_Width | DWS | Ramp_Type | Running_Slope |
|------------------|------------|----------|----------------|----------------|--|----------------------------------|------------------------|
| 2023047 | 47 | Point ZM | Very Poor | 48" or greater | No DWS (Non-Compliant) | Unknown | Up to or equal to 8.3% |
| 2023048 | 48 | Point ZM | Very Poor | 36" to > 48" | Old Standard (Diamond/Exposed Aggregate) | Blended Transition | Up to or equal to 8.3% |
| 2023049 | 49 | Point ZM | Very Poor | Less than 36" | Old Standard (Diamond/Exposed Aggregate) | Perpendicular (triangular wings) | Up to or equal to 8.3% |
| 2023050 | 50 | Point ZM | Fair or Better | 48" or greater | Compliant (Truncated Domes with Contrasting Color) | Perpendicular (triangular wings) | Up to or equal to 8.3% |
| 2023051 | 51 | Point ZM | Fair or Better | 48" or greater | Compliant (Truncated Domes with Contrasting Color) | Perpendicular (triangular wings) | Up to or equal to 8.3% |
| 2023052 | 52 | Point ZM | Fair or Better | 48" or greater | Compliant (Truncated Domes with Contrasting Color) | Parallel-Single Direction | Up to or equal to 8.3% |
| 2023053 | 53 | Point ZM | Fair or Better | 48" or greater | Compliant (Truncated Domes with Contrasting Color) | Blended Transition | Up to or equal to 8.3% |
| 2023054 | 55 | Point ZM | Fair or Better | 48" or greater | Compliant (Truncated Domes with Contrasting Color) | Parallel-Single Direction | Up to or equal to 8.3% |
| 2023055 | 56 | Point ZM | Fair or Better | 48" or greater | Compliant (Truncated Domes with Contrasting Color) | Combination | Up to or equal to 8.3% |
| 2023056 | 57 | Point ZM | Fair or Better | 48" or greater | Compliant (Truncated Domes with Contrasting Color) | Parallel-Single Direction | Up to or equal to 8.3% |
| 2023057 | 58 | Point ZM | Fair or Better | 48" or greater | Compliant (Truncated Domes with Contrasting Color) | Parallel-Single Direction | Up to or equal to 8.3% |
| 2023058 | 59 | Point ZM | Fair or Better | 48" or greater | Compliant (Truncated Domes with Contrasting Color) | Parallel-Diagonally Oriented | Up to or equal to 8.3% |
| 2023059 | 60 | Point ZM | Fair or Better | 48" or greater | Compliant (Truncated Domes with Contrasting Color) | Parallel-Diagonally Oriented | Up to or equal to 8.3% |
| 2023060 | 61 | Point ZM | Fair or Better | 48" or greater | Compliant (Truncated Domes with Contrasting Color) | Parallel-Diagonally Oriented | Up to or equal to 8.3% |
| 2023061 | 62 | Point ZM | Fair or Better | 48" or greater | Compliant (Truncated Domes with Contrasting Color) | Combination | Up to or equal to 8.3% |
| 2023062 | 63 | Point ZM | Fair or Better | 48" or greater | Compliant (Truncated Domes with Contrasting Color) | Combination | Up to or equal to 8.3% |
| 2023063 | 64 | Point ZM | Fair or Better | 48" or greater | Compliant (Truncated Domes with Contrasting Color) | Parallel-Diagonally Oriented | Up to or equal to 8.3% |
| 2023064 | 65 | Point ZM | Fair or Better | 48" or greater | Compliant (Truncated Domes with Contrasting Color) | Parallel-Diagonally Oriented | Up to or equal to 8.3% |
| 2023065 | 66 | Point ZM | Fair or Better | 48" or greater | Compliant (Truncated Domes with Contrasting Color) | Parallel-Single Direction | Up to or equal to 8.3% |
| 2023066 | 67 | Point ZM | Fair or Better | 48" or greater | Compliant (Truncated Domes with Contrasting Color) | Parallel-Single Direction | Up to or equal to 8.3% |
| 2023067 | 68 | Point ZM | Fair or Better | 48" or greater | Compliant (Truncated Domes with Contrasting Color) | Parallel-Single Direction | Up to or equal to 8.3% |
| 2023068 | 69 | Point ZM | Fair or Better | 48" or greater | Compliant (Truncated Domes with Contrasting Color) | Parallel-Single Direction | Up to or equal to 8.3% |
| 2023069 | 70 | Point ZM | Fair or Better | 48" or greater | Compliant (Truncated Domes with Contrasting Color) | Parallel-Single Direction | Up to or equal to 8.3% |
| 2023070 | 71 | Point ZM | Fair or Better | 48" or greater | Compliant (Truncated Domes with Contrasting Color) | Parallel-Single Direction | Up to or equal to 8.3% |
| 2023071 | 72 | Point ZM | Fair or Better | 48" or greater | Compliant (Truncated Domes with Contrasting Color) | Parallel-Single Direction | Up to or equal to 8.3% |
| 2023072 | 73 | Point ZM | Fair or Better | 48" or greater | Compliant (Truncated Domes with Contrasting Color) | Parallel-Single Direction | Up to or equal to 8.3% |
| 2023073 | 74 | Point ZM | Fair or Better | 48" or greater | Compliant (Truncated Domes with Contrasting Color) | Parallel-Single Direction | Up to or equal to 8.3% |
| 2023074 | 75 | Point ZM | Fair or Better | 48" or greater | Compliant (Truncated Domes with Contrasting Color) | Parallel-Single Direction | Up to or equal to 8.3% |
| 2023075 | 76 | Point ZM | Fair or Better | 48" or greater | Compliant (Truncated Domes with Contrasting Color) | Parallel-Single Direction | Up to or equal to 8.3% |
| 2023076 | 77 | Point ZM | Fair or Better | 48" or greater | Compliant (Truncated Domes with Contrasting Color) | Parallel-Single Direction | Up to or equal to 8.3% |
| 2023077 | 78 | Point ZM | Fair or Better | 48" or greater | Compliant (Truncated Domes with Contrasting Color) | Parallel-Single Direction | Up to or equal to 8.3% |
| 2023078 | 79 | Point ZM | Fair or Better | 48" or greater | Compliant (Truncated Domes with Contrasting Color) | Parallel-Single Direction | Up to or equal to 8.3% |
| 2023079 | 80 | Point ZM | Fair or Better | 48" or greater | Compliant (Truncated Domes with Contrasting Color) | Parallel-Single Direction | Up to or equal to 8.3% |
| 2023080 | 81 | Point ZM | Fair or Better | 48" or greater | Compliant (Truncated Domes with Contrasting Color) | Parallel-Single Direction | Up to or equal to 8.3% |
| 2023081 | 82 | Point ZM | Very Poor | 36" to > 48" | Compliant (Truncated Domes with Contrasting Color) | Unknown | More than 8.3% |
| 2023082 | 83 | Point ZM | Very Poor | 36" to > 48" | Compliant (Truncated Domes with Contrasting Color) | Unknown | More than 8.3% |
| 2023083 | 84 | Point ZM | Very Poor | 48" or greater | Compliant (Truncated Domes with Contrasting Color) | Combination | More than 8.3% |
| 2023084 | 85 | Point ZM | Very Poor | 48" or greater | Compliant (Truncated Domes with Contrasting Color) | Combination | Up to or equal to 8.3% |
| 2023085 | 86 | Point ZM | Very Poor | 48" or greater | Compliant (Truncated Domes with Contrasting Color) | Unknown | Up to or equal to 8.3% |
| 2023086 | 87 | Point ZM | Fair or Better | 48" or greater | Compliant (Truncated Domes with Contrasting Color) | Perpendicular (triangular wings) | More than 8.3% |
| 2023087 | 88 | Point ZM | Fair or Better | 48" or greater | Compliant (Truncated Domes with Contrasting Color) | Parallel-Single Direction | Up to or equal to 8.3% |
| 2023088 | 89 | Point ZM | Poor | 48" or greater | Compliant (Truncated Domes with Contrasting Color) | Perpendicular (triangular wings) | More than 8.3% |
| 2023089 | 90 | Point ZM | Poor | 48" or greater | Compliant (Truncated Domes with Contrasting Color) | Perpendicular (triangular wings) | Up to or equal to 8.3% |
| 2023090 | 91 | Point ZM | Poor | 48" or greater | Compliant (Truncated Domes with Contrasting Color) | Parallel-Single Direction | Up to or equal to 8.3% |
| 2023091 | 94 | Point ZM | Very Poor | 48" or greater | Compliant (Truncated Domes with Contrasting Color) | Combination | More than 8.3% |
| 2023092 | 95 | Point ZM | Poor | 48" or greater | Compliant (Truncated Domes with Contrasting Color) | Combination | Up to or equal to 8.3% |

City of Sultan
2023 ADA Access Plan GIS Curb Ramp Inventory

| TSI_Curb_Ramp_ID | OBJECTID * | SHAPE * | Condition * | Ramp_Width | DWS | Ramp_Type | Running_Slope |
|------------------|------------|----------|-------------------------------------|----------------|--|----------------------------------|------------------------|
| 2023139 | 149 | Point ZM | Very Poor | Less than 36" | Old Standard (Diamond/Exposed Aggregate) | Unknown | More than 8.3% |
| 2023140 | 150 | Point ZM | Very Poor | Less than 36" | Old Standard (Diamond/Exposed Aggregate) | Unknown | More than 8.3% |
| 2023141 | 141 | Point ZM | Poor | 48" or greater | Compliant (Truncated Domes with Contrasting Color) | Combination | Up to or equal to 8.3% |
| 2023142 | 142 | Point ZM | Missing (needed but does not exist) | <Null> | <Null> | <Null> | <Null> |
| 2023143 | 143 | Point ZM | Poor | 36" to > 48" | Old Standard (Diamond/Exposed Aggregate) | Perpendicular (triangular wings) | More than 8.3% |
| 2023144 | 151 | Point ZM | Very Poor | Less than 36" | Old Standard (Diamond/Exposed Aggregate) | Unknown | Up to or equal to 8.3% |
| 2023145 | 54 | Point ZM | Fair or Better | 48" or greater | Compliant (Truncated Domes with Contrasting Color) | Parallel-Single Direction | Up to or equal to 8.3% |
| 2023146 | 117 | Point ZM | Missing (needed but does not exist) | <Null> | <Null> | <Null> | <Null> |
| 2023147 | 116 | Point ZM | Missing (needed but does not exist) | <Null> | <Null> | <Null> | <Null> |
| 2023148 | 140 | Point ZM | Missing (needed but does not exist) | <Null> | <Null> | <Null> | <Null> |
| 2023149 | 139 | Point ZM | Missing (needed but does not exist) | <Null> | <Null> | <Null> | <Null> |
| 2023150 | 93 | Point ZM | Missing (needed but does not exist) | <Null> | <Null> | <Null> | <Null> |
| 2023151 | 92 | Point ZM | Missing (needed but does not exist) | <Null> | <Null> | <Null> | <Null> |
| 2023152 | 152 | Point ZM | Fair or Better | 48" or greater | Compliant (Truncated Domes with Contrasting Color) | Parallel-Single Direction | Up to or equal to 8.3% |
| 2023153 | 153 | Point ZM | Fair or Better | 48" or greater | Compliant (Truncated Domes with Contrasting Color) | Parallel-Single Direction | Up to or equal to 8.3% |
| 2023154 | 154 | Point ZM | Fair or Better | 48" or greater | Compliant (Truncated Domes with Contrasting Color) | Parallel-Single Direction | Up to or equal to 8.3% |
| 2023155 | 155 | Point ZM | Fair or Better | 48" or greater | Compliant (Truncated Domes with Contrasting Color) | Parallel-Single Direction | Up to or equal to 8.3% |
| 2023156 | 158 | Point ZM | Fair or Better | 48" or greater | Compliant (Truncated Domes with Contrasting Color) | Parallel-Single Direction | Up to or equal to 8.3% |
| 2023157 | 160 | Point ZM | Fair or Better | 48" or greater | Compliant (Truncated Domes with Contrasting Color) | Perpendicular (triangular wings) | Up to or equal to 8.3% |
| 2023158 | 161 | Point ZM | Fair or Better | 48" or greater | Compliant (Truncated Domes with Contrasting Color) | Perpendicular (triangular wings) | Up to or equal to 8.3% |
| 2023159 | 163 | Point ZM | Poor | 36" to > 48" | Old Standard (Diamond/Exposed Aggregate) | Perpendicular (triangular wings) | More than 8.3% |
| 2023160 | 164 | Point ZM | Poor | 36" to > 48" | Old Standard (Diamond/Exposed Aggregate) | Perpendicular (triangular wings) | Up to or equal to 8.3% |
| 2023161 | 166 | Point ZM | Very Poor | 36" to > 48" | Old Standard (Diamond/Exposed Aggregate) | Perpendicular (triangular wings) | Up to or equal to 8.3% |
| 2023162 | 167 | Point ZM | Very Poor | 36" to > 48" | Old Standard (Diamond/Exposed Aggregate) | Perpendicular (triangular wings) | Up to or equal to 8.3% |
| 2023163 | 169 | Point ZM | Very Poor | 36" to > 48" | Old Standard (Diamond/Exposed Aggregate) | Unknown | More than 8.3% |
| 2023164 | 170 | Point ZM | Missing (needed but does not exist) | <Null> | <Null> | <Null> | <Null> |
| 2023165 | 171 | Point ZM | Poor | 36" to > 48" | Old Standard (Diamond/Exposed Aggregate) | Perpendicular (triangular wings) | More than 8.3% |
| 2023166 | 172 | Point ZM | Very Poor | 36" to > 48" | Old Standard (Diamond/Exposed Aggregate) | Perpendicular (triangular wings) | More than 8.3% |
| 2023167 | 173 | Point ZM | Very Poor | 36" to > 48" | Old Standard (Diamond/Exposed Aggregate) | Perpendicular (triangular wings) | More than 8.3% |
| 2023168 | 601 | Point ZM | Missing (needed but does not exist) | <Null> | <Null> | <Null> | <Null> |
| 2023169 | 602 | Point ZM | Missing (needed but does not exist) | <Null> | <Null> | <Null> | <Null> |
| 2023170 | 603 | Point ZM | Very Poor | 36" to > 48" | Old Standard (Diamond/Exposed Aggregate) | Perpendicular (triangular wings) | More than 8.3% |
| 2023171 | 188 | Point ZM | Very Poor | 36" to > 48" | Old Standard (Diamond/Exposed Aggregate) | Unknown | Up to or equal to 8.3% |
| 2023172 | 179 | Point ZM | Poor | 36" to > 48" | Old Standard (Diamond/Exposed Aggregate) | Perpendicular (triangular wings) | More than 8.3% |
| 2023173 | 180 | Point ZM | Poor | 36" to > 48" | Old Standard (Diamond/Exposed Aggregate) | Perpendicular (triangular wings) | More than 8.3% |
| 2023174 | 181 | Point ZM | Poor | 36" to > 48" | Old Standard (Diamond/Exposed Aggregate) | Perpendicular (triangular wings) | More than 8.3% |
| 2023175 | 182 | Point ZM | Poor | 36" to > 48" | Old Standard (Diamond/Exposed Aggregate) | Perpendicular (triangular wings) | More than 8.3% |
| 2023176 | 183 | Point ZM | Very Poor | Less than 36" | No DWS (Non-Compliant) | Unknown | Up to or equal to 8.3% |
| 2023177 | 184 | Point ZM | Very Poor | Less than 36" | No DWS (Non-Compliant) | Unknown | Up to or equal to 8.3% |
| 2023178 | 185 | Point ZM | Very Poor | 36" to > 48" | Old Standard (Diamond/Exposed Aggregate) | Unknown | More than 8.3% |
| 2023179 | 186 | Point ZM | Very Poor | 36" to > 48" | Old Standard (Diamond/Exposed Aggregate) | Unknown | Up to or equal to 8.3% |
| 2023180 | 187 | Point ZM | Very Poor | 36" to > 48" | No DWS (Non-Compliant) | Unknown | Up to or equal to 8.3% |
| 2023181 | 189 | Point ZM | Very Poor | 36" to > 48" | Old Standard (Diamond/Exposed Aggregate) | Unknown | Up to or equal to 8.3% |
| 2023182 | 190 | Point ZM | Very Poor | 36" to > 48" | Old Standard (Diamond/Exposed Aggregate) | Unknown | Up to or equal to 8.3% |
| 2023183 | 191 | Point ZM | Very Poor | 36" to > 48" | Old Standard (Diamond/Exposed Aggregate) | Unknown | More than 8.3% |
| 2023184 | 192 | Point ZM | Very Poor | 36" to > 48" | Old Standard (Diamond/Exposed Aggregate) | Unknown | Up to or equal to 8.3% |

City of Sultan
2023 ADA Access Plan GIS Curb Ramp Inventory

| TSI_Curb_Ramp_ID | OBJECTID * | SHAPE * | Condition * | Ramp_Width | DWS | Ramp_Type | Running_Slope |
|------------------|------------|----------|-------------------------------------|----------------|--|----------------------------------|------------------------|
| 2023185 | 193 | Point ZM | Very Poor | Less than 36" | Old Standard (Diamond/Exposed Aggregate) | Unknown | More than 8.3% |
| 2023186 | 194 | Point ZM | Very Poor | 36" to > 48" | Old Standard (Diamond/Exposed Aggregate) | Unknown | Up to or equal to 8.3% |
| 2023187 | 195 | Point ZM | Very Poor | 36" to > 48" | Old Standard (Diamond/Exposed Aggregate) | Unknown | Up to or equal to 8.3% |
| 2023188 | 197 | Point ZM | Fair or Better | 48" or greater | Compliant (Truncated Domes with Contrasting Color) | Combination | Up to or equal to 8.3% |
| 2023189 | 198 | Point ZM | Fair or Better | 48" or greater | Compliant (Truncated Domes with Contrasting Color) | Parallel-Single Direction | Up to or equal to 8.3% |
| 2023190 | 202 | Point ZM | Fair or Better | 36" to > 48" | Compliant (Truncated Domes with Contrasting Color) | Combination | Up to or equal to 8.3% |
| 2023191 | 203 | Point ZM | Fair or Better | 48" or greater | Compliant (Truncated Domes with Contrasting Color) | Combination | Up to or equal to 8.3% |
| 2023192 | 216 | Point ZM | Fair or Better | 48" or greater | Compliant (Truncated Domes with Contrasting Color) | Parallel-Single Direction | Up to or equal to 8.3% |
| 2023193 | 206 | Point ZM | Very Poor | 36" to > 48" | Old Standard (Diamond/Exposed Aggregate) | Parallel-Single Direction | More than 8.3% |
| 2023194 | 210 | Point ZM | Very Poor | 36" to > 48" | Old Standard (Diamond/Exposed Aggregate) | Perpendicular (triangular wings) | More than 8.3% |
| 2023195 | 211 | Point ZM | Very Poor | 36" to > 48" | Old Standard (Diamond/Exposed Aggregate) | Perpendicular (triangular wings) | Up to or equal to 8.3% |
| 2023196 | 219 | Point ZM | Missing (needed but does not exist) | <Null> | <Null> | <Null> | <Null> |
| 2023197 | 220 | Point ZM | Very Poor | 36" to > 48" | Old Standard (Diamond/Exposed Aggregate) | Perpendicular (triangular wings) | More than 8.3% |
| 2023198 | 212 | Point ZM | Very Poor | 36" to > 48" | Old Standard (Diamond/Exposed Aggregate) | Perpendicular (triangular wings) | More than 8.3% |
| 2023199 | 213 | Point ZM | Very Poor | 36" to > 48" | Old Standard (Diamond/Exposed Aggregate) | Perpendicular (triangular wings) | More than 8.3% |
| 2023200 | 225 | Point ZM | Fair or Better | 36" to > 48" | Compliant (Truncated Domes with Contrasting Color) | Combination | Up to or equal to 8.3% |
| 2023201 | 226 | Point ZM | Fair or Better | 48" or greater | Compliant (Truncated Domes with Contrasting Color) | Combination | Up to or equal to 8.3% |
| 2023202 | 227 | Point ZM | Very Poor | 36" to > 48" | Old Standard (Diamond/Exposed Aggregate) | Perpendicular (triangular wings) | Up to or equal to 8.3% |
| 2023203 | 228 | Point ZM | Very Poor | 36" to > 48" | Old Standard (Diamond/Exposed Aggregate) | <Null> | Up to or equal to 8.3% |
| 2023204 | 230 | Point ZM | Very Poor | Less than 36" | Old Standard (Diamond/Exposed Aggregate) | Unknown | More than 8.3% |
| 2023205 | 231 | Point ZM | Very Poor | Less than 36" | Old Standard (Diamond/Exposed Aggregate) | Unknown | More than 8.3% |
| 2023206 | 232 | Point ZM | Poor | 36" to > 48" | Compliant (Truncated Domes with Contrasting Color) | Unknown | More than 8.3% |
| 2023207 | 233 | Point ZM | Very Poor | Less than 36" | Old Standard (Diamond/Exposed Aggregate) | Unknown | More than 8.3% |
| 2023208 | 234 | Point ZM | Fair or Better | 48" or greater | Compliant (Truncated Domes with Contrasting Color) | Parallel-Single Direction | Up to or equal to 8.3% |
| 2023209 | 235 | Point ZM | Fair or Better | 48" or greater | Compliant (Truncated Domes with Contrasting Color) | Unknown | Up to or equal to 8.3% |
| 2023210 | 237 | Point ZM | Very Poor | Less than 36" | Old Standard (Diamond/Exposed Aggregate) | Perpendicular (triangular wings) | More than 8.3% |
| 2023211 | 238 | Point ZM | Poor | 36" to > 48" | Old Standard (Diamond/Exposed Aggregate) | Perpendicular (triangular wings) | More than 8.3% |
| 2023212 | 239 | Point ZM | Poor | 36" to > 48" | Old Standard (Diamond/Exposed Aggregate) | Perpendicular (triangular wings) | Up to or equal to 8.3% |
| 2023213 | 240 | Point ZM | Fair or Better | 48" or greater | Compliant (Truncated Domes with Contrasting Color) | Perpendicular (triangular wings) | Up to or equal to 8.3% |
| 2023214 | 241 | Point ZM | Very Poor | 36" to > 48" | Old Standard (Diamond/Exposed Aggregate) | Combination | More than 8.3% |
| 2023215 | 242 | Point ZM | Very Poor | 36" to > 48" | Old Standard (Diamond/Exposed Aggregate) | Combination | Up to or equal to 8.3% |
| 2023216 | 243 | Point ZM | Poor | 36" to > 48" | Old Standard (Diamond/Exposed Aggregate) | Perpendicular (triangular wings) | Up to or equal to 8.3% |
| 2023217 | 244 | Point ZM | Very Poor | 36" to > 48" | Old Standard (Diamond/Exposed Aggregate) | Combination | More than 8.3% |
| 2023218 | 245 | Point ZM | Very Poor | 36" to > 48" | Old Standard (Diamond/Exposed Aggregate) | Combination | Up to or equal to 8.3% |
| 2023219 | 247 | Point ZM | Very Poor | 36" to > 48" | Old Standard (Diamond/Exposed Aggregate) | Combination | More than 8.3% |
| 2023220 | 248 | Point ZM | Very Poor | Less than 36" | Old Standard (Diamond/Exposed Aggregate) | Unknown | Up to or equal to 8.3% |
| 2023221 | 249 | Point ZM | Very Poor | 36" to > 48" | Old Standard (Diamond/Exposed Aggregate) | Unknown | Up to or equal to 8.3% |
| 2023222 | 250 | Point ZM | Very Poor | 36" to > 48" | Old Standard (Diamond/Exposed Aggregate) | Unknown | Up to or equal to 8.3% |
| 2023223 | 156 | Point ZM | Fair or Better | 48" or greater | Compliant (Truncated Domes with Contrasting Color) | Parallel-Single Direction | Up to or equal to 8.3% |
| 2023224 | 162 | Point ZM | Fair or Better | 48" or greater | Compliant (Truncated Domes with Contrasting Color) | Perpendicular (triangular wings) | Up to or equal to 8.3% |
| 2023225 | 196 | Point ZM | Very Poor | 36" to > 48" | Old Standard (Diamond/Exposed Aggregate) | Combination | Up to or equal to 8.3% |
| 2023226 | 200 | Point ZM | Fair or Better | 48" or greater | Compliant (Truncated Domes with Contrasting Color) | Combination | Up to or equal to 8.3% |
| 2023227 | 201 | Point ZM | Fair or Better | 48" or greater | Compliant (Truncated Domes with Contrasting Color) | Combination | Up to or equal to 8.3% |
| 2023228 | 204 | Point ZM | Very Poor | 36" to > 48" | Old Standard (Diamond/Exposed Aggregate) | Unknown | More than 8.3% |
| 2023229 | 205 | Point ZM | Very Poor | 36" to > 48" | Old Standard (Diamond/Exposed Aggregate) | Unknown | Up to or equal to 8.3% |
| 2023230 | 207 | Point ZM | Very Poor | 36" to > 48" | Old Standard (Diamond/Exposed Aggregate) | Unknown | More than 8.3% |

City of Sultan
2023 ADA Access Plan GIS Curb Ramp Inventory

| TSI_Curb_Ramp_ID | OBJECTID * | SHAPE * | Condition * | Ramp_Width | DWS | Ramp_Type | Running_Slope |
|------------------|------------|----------|-------------------------------------|----------------|--|----------------------------------|------------------------|
| 2023231 | 217 | Point ZM | Fair or Better | 48" or greater | Compliant (Truncated Domes with Contrasting Color) | Combination | Up to or equal to 8.3% |
| 2023232 | 218 | Point ZM | Fair or Better | 48" or greater | Compliant (Truncated Domes with Contrasting Color) | Parallel-Single Direction | Up to or equal to 8.3% |
| 2023233 | 221 | Point ZM | Missing (needed but does not exist) | <Null> | <Null> | <Null> | <Null> |
| 2023234 | 223 | Point ZM | Very Poor | 36" to > 48" | Old Standard (Diamond/Exposed Aggregate) | Perpendicular (triangular wings) | More than 8.3% |
| 2023235 | 224 | Point ZM | Very Poor | 36" to > 48" | Old Standard (Diamond/Exposed Aggregate) | Unknown | More than 8.3% |
| 2023236 | 236 | Point ZM | Fair or Better | 48" or greater | Compliant (Truncated Domes with Contrasting Color) | Unknown | Up to or equal to 8.3% |
| 2023237 | 246 | Point ZM | Very Poor | 36" to > 48" | Old Standard (Diamond/Exposed Aggregate) | Combination | More than 8.3% |
| 2023238 | 157 | Point ZM | Missing (needed but does not exist) | <Null> | <Null> | <Null> | <Null> |
| 2023239 | 159 | Point ZM | Missing (needed but does not exist) | <Null> | <Null> | <Null> | <Null> |
| 2023240 | 165 | Point ZM | Missing (needed but does not exist) | <Null> | <Null> | <Null> | <Null> |
| 2023241 | 168 | Point ZM | Missing (needed but does not exist) | <Null> | <Null> | <Null> | <Null> |
| 2023242 | 174 | Point ZM | Missing (needed but does not exist) | <Null> | <Null> | <Null> | <Null> |
| 2023243 | 600 | Point ZM | Poor | 36" to > 48" | Old Standard (Diamond/Exposed Aggregate) | Perpendicular (triangular wings) | More than 8.3% |
| 2023244 | 199 | Point ZM | Missing (needed but does not exist) | <Null> | <Null> | <Null> | <Null> |
| 2023245 | 208 | Point ZM | Missing (needed but does not exist) | <Null> | <Null> | <Null> | <Null> |
| 2023246 | 209 | Point ZM | Poor | 48" or greater | Old Standard (Diamond/Exposed Aggregate) | Unknown | More than 8.3% |
| 2023247 | 214 | Point ZM | Missing (needed but does not exist) | <Null> | <Null> | <Null> | <Null> |
| 2023248 | 215 | Point ZM | Missing (needed but does not exist) | <Null> | <Null> | <Null> | <Null> |
| 2023249 | 222 | Point ZM | Missing (needed but does not exist) | <Null> | <Null> | <Null> | <Null> |
| 2023250 | 229 | Point ZM | Missing (needed but does not exist) | <Null> | <Null> | <Null> | <Null> |
| 2023251 | 251 | Point ZM | Fair or Better | 48" or greater | Compliant (Truncated Domes with Contrasting Color) | Parallel-Single Direction | Up to or equal to 8.3% |
| 2023252 | 252 | Point ZM | Fair or Better | 48" or greater | Compliant (Truncated Domes with Contrasting Color) | Perpendicular (triangular wings) | Up to or equal to 8.3% |
| 2023253 | 253 | Point ZM | Fair or Better | 48" or greater | Compliant (Truncated Domes with Contrasting Color) | Perpendicular (triangular wings) | More than 8.3% |
| 2023254 | 254 | Point ZM | Fair or Better | 48" or greater | Compliant (Truncated Domes with Contrasting Color) | Parallel-Single Direction | Up to or equal to 8.3% |
| 2023255 | 255 | Point ZM | Fair or Better | 48" or greater | Compliant (Truncated Domes with Contrasting Color) | Parallel-Single Direction | Up to or equal to 8.3% |
| 2023256 | 256 | Point ZM | Fair or Better | 48" or greater | Compliant (Truncated Domes with Contrasting Color) | Parallel-Single Direction | Up to or equal to 8.3% |
| 2023257 | 257 | Point ZM | Fair or Better | 48" or greater | Compliant (Truncated Domes with Contrasting Color) | Parallel-Single Direction | Up to or equal to 8.3% |
| 2023258 | 258 | Point ZM | Fair or Better | 48" or greater | Compliant (Truncated Domes with Contrasting Color) | Parallel-Single Direction | Up to or equal to 8.3% |
| 2023259 | 259 | Point ZM | Fair or Better | 48" or greater | Compliant (Truncated Domes with Contrasting Color) | Parallel-Single Direction | Up to or equal to 8.3% |
| 2023260 | 260 | Point ZM | Fair or Better | 48" or greater | Compliant (Truncated Domes with Contrasting Color) | Parallel-Single Direction | Up to or equal to 8.3% |
| 2023261 | 261 | Point ZM | Fair or Better | 48" or greater | Compliant (Truncated Domes with Contrasting Color) | Parallel-Diagonally Oriented | Up to or equal to 8.3% |
| 2023262 | 262 | Point ZM | Fair or Better | 48" or greater | Compliant (Truncated Domes with Contrasting Color) | Parallel-Diagonally Oriented | Up to or equal to 8.3% |
| 2023263 | 263 | Point ZM | Fair or Better | 48" or greater | Compliant (Truncated Domes with Contrasting Color) | Parallel-Diagonally Oriented | Up to or equal to 8.3% |
| 2023264 | 264 | Point ZM | Fair or Better | 48" or greater | Compliant (Truncated Domes with Contrasting Color) | Parallel-Single Direction | Up to or equal to 8.3% |
| 2023265 | 265 | Point ZM | Fair or Better | 48" or greater | Compliant (Truncated Domes with Contrasting Color) | Parallel-Diagonally Oriented | Up to or equal to 8.3% |
| 2023266 | 266 | Point ZM | Fair or Better | 48" or greater | Compliant (Truncated Domes with Contrasting Color) | Parallel-Single Direction | Up to or equal to 8.3% |
| 2023267 | 267 | Point ZM | Fair or Better | 48" or greater | Compliant (Truncated Domes with Contrasting Color) | Parallel-Single Direction | Up to or equal to 8.3% |
| 2023268 | 268 | Point ZM | Fair or Better | 48" or greater | Compliant (Truncated Domes with Contrasting Color) | Parallel-Single Direction | Up to or equal to 8.3% |
| 2023269 | 269 | Point ZM | Fair or Better | 48" or greater | Compliant (Truncated Domes with Contrasting Color) | Parallel-Single Direction | Up to or equal to 8.3% |
| 2023270 | 270 | Point ZM | Missing (needed but does not exist) | <Null> | <Null> | <Null> | <Null> |
| 2023271 | 271 | Point ZM | Poor | 36" to > 48" | Old Standard (Diamond/Exposed Aggregate) | Perpendicular (triangular wings) | More than 8.3% |
| 2023272 | 272 | Point ZM | Poor | 36" to > 48" | Old Standard (Diamond/Exposed Aggregate) | Perpendicular (triangular wings) | More than 8.3% |
| 2023273 | 273 | Point ZM | Poor | 36" to > 48" | Old Standard (Diamond/Exposed Aggregate) | Perpendicular (triangular wings) | More than 8.3% |
| 2023274 | 274 | Point ZM | Missing (needed but does not exist) | <Null> | <Null> | <Null> | <Null> |
| 2023275 | 275 | Point ZM | Missing (needed but does not exist) | <Null> | <Null> | <Null> | <Null> |

City of Sultan
2023 ADA Access Plan GIS Curb Ramp Inventory

| TSI_Curb_Ramp_ID | OBJECTID * | SHAPE * | Condition * | Ramp_Width | DWS | Ramp_Type | Running_Slope |
|------------------|------------|----------|-------------------------------------|----------------|--|----------------------------------|------------------------|
| 2023276 | 276 | Point ZM | Poor | 36" to > 48" | Old Standard (Diamond/Exposed Aggregate) | Perpendicular (triangular wings) | Up to or equal to 8.3% |
| 2023277 | 277 | Point ZM | Poor | 48" or greater | Old Standard (Diamond/Exposed Aggregate) | Perpendicular (triangular wings) | More than 8.3% |
| 2023278 | 278 | Point ZM | Fair or Better | 48" or greater | Compliant (Truncated Domes with Contrasting Color) | Perpendicular (triangular wings) | More than 8.3% |
| 2023279 | 279 | Point ZM | Fair or Better | 48" or greater | Compliant (Truncated Domes with Contrasting Color) | Perpendicular (triangular wings) | Up to or equal to 8.3% |
| 2023280 | 280 | Point ZM | Missing (needed but does not exist) | <Null> | <Null> | <Null> | <Null> |
| 2023281 | 281 | Point ZM | Fair or Better | 48" or greater | Compliant (Truncated Domes with Contrasting Color) | Parallel-Single Direction | Up to or equal to 8.3% |
| 2023282 | 282 | Point ZM | Fair or Better | 48" or greater | Compliant (Truncated Domes with Contrasting Color) | Parallel-Single Direction | Up to or equal to 8.3% |
| 2023283 | 283 | Point ZM | Fair or Better | 48" or greater | Compliant (Truncated Domes with Contrasting Color) | Parallel-Single Direction | Up to or equal to 8.3% |
| 2023284 | 284 | Point ZM | Fair or Better | 48" or greater | Compliant (Truncated Domes with Contrasting Color) | Parallel-Single Direction | Up to or equal to 8.3% |
| 2023285 | 285 | Point ZM | Very Poor | <Null> | <Null> | Blended Transition | <Null> |
| 2023286 | 286 | Point ZM | Fair or Better | 48" or greater | Compliant (Truncated Domes with Contrasting Color) | Perpendicular (triangular wings) | Up to or equal to 8.3% |
| 2023287 | 287 | Point ZM | Fair or Better | 48" or greater | Compliant (Truncated Domes with Contrasting Color) | Parallel-Single Direction | Up to or equal to 8.3% |
| 2023288 | 288 | Point ZM | Fair or Better | 48" or greater | Compliant (Truncated Domes with Contrasting Color) | Combination | Up to or equal to 8.3% |
| 2023289 | 289 | Point ZM | Fair or Better | 48" or greater | Compliant (Truncated Domes with Contrasting Color) | Perpendicular (triangular wings) | Up to or equal to 8.3% |
| 2023290 | 290 | Point ZM | Fair or Better | 48" or greater | Compliant (Truncated Domes with Contrasting Color) | Perpendicular (triangular wings) | Up to or equal to 8.3% |
| 2023291 | 291 | Point ZM | Fair or Better | 48" or greater | Compliant (Truncated Domes with Contrasting Color) | Parallel-Single Direction | Up to or equal to 8.3% |
| 2023292 | 292 | Point ZM | Fair or Better | 48" or greater | Compliant (Truncated Domes with Contrasting Color) | Parallel-Single Direction | Up to or equal to 8.3% |
| 2023293 | 293 | Point ZM | Fair or Better | 48" or greater | Compliant (Truncated Domes with Contrasting Color) | Parallel-Single Direction | Up to or equal to 8.3% |
| 2023294 | 294 | Point ZM | Missing (needed but does not exist) | <Null> | <Null> | <Null> | <Null> |
| 2023295 | 295 | Point ZM | Fair or Better | 48" or greater | Compliant (Truncated Domes with Contrasting Color) | Perpendicular (triangular wings) | More than 8.3% |
| 2023296 | 296 | Point ZM | Fair or Better | 48" or greater | Compliant (Truncated Domes with Contrasting Color) | Perpendicular (triangular wings) | More than 8.3% |
| 2023297 | 297 | Point ZM | Fair or Better | 48" or greater | Compliant (Truncated Domes with Contrasting Color) | Perpendicular (triangular wings) | More than 8.3% |
| 2023298 | 298 | Point ZM | Fair or Better | 48" or greater | Compliant (Truncated Domes with Contrasting Color) | Perpendicular (triangular wings) | Up to or equal to 8.3% |
| 2023299 | 299 | Point ZM | Missing (needed but does not exist) | <Null> | <Null> | Blended Transition | <Null> |
| 2023300 | 300 | Point ZM | Fair or Better | 48" or greater | Compliant (Truncated Domes with Contrasting Color) | Perpendicular (triangular wings) | Up to or equal to 8.3% |
| 2023301 | 301 | Point ZM | Fair or Better | 48" or greater | Compliant (Truncated Domes with Contrasting Color) | Perpendicular (triangular wings) | Up to or equal to 8.3% |
| 2023302 | 302 | Point ZM | Missing (needed but does not exist) | <Null> | <Null> | Blended Transition | <Null> |
| 2023303 | 303 | Point ZM | Poor | 48" or greater | <Null> | Perpendicular (triangular wings) | Up to or equal to 8.3% |
| 2023304 | 304 | Point ZM | Fair or Better | 48" or greater | Compliant (Truncated Domes with Contrasting Color) | Unknown | Up to or equal to 8.3% |
| 2023305 | 305 | Point ZM | Fair or Better | 48" or greater | Compliant (Truncated Domes with Contrasting Color) | Combination | Up to or equal to 8.3% |
| 2023306 | 596 | Point ZM | Poor | 36" to > 48" | Old Standard (Diamond/Exposed Aggregate) | Perpendicular (triangular wings) | More than 8.3% |
| 2023307 | 307 | Point ZM | Fair or Better | 48" or greater | Compliant (Truncated Domes with Contrasting Color) | Parallel-Single Direction | Up to or equal to 8.3% |
| 2023308 | 308 | Point ZM | Fair or Better | 48" or greater | Compliant (Truncated Domes with Contrasting Color) | Parallel-Single Direction | Up to or equal to 8.3% |
| 2023309 | 309 | Point ZM | Missing (needed but does not exist) | <Null> | <Null> | <Null> | <Null> |
| 2023310 | 310 | Point ZM | Missing (needed but does not exist) | <Null> | <Null> | <Null> | <Null> |
| 2023311 | 311 | Point ZM | Fair or Better | 48" or greater | Compliant (Truncated Domes with Contrasting Color) | Parallel-Single Direction | Up to or equal to 8.3% |
| 2023312 | 597 | Point ZM | Poor | 36" to > 48" | Old Standard (Diamond/Exposed Aggregate) | Perpendicular (triangular wings) | Up to or equal to 8.3% |
| 2023313 | 313 | Point ZM | Fair or Better | 48" or greater | Compliant (Truncated Domes with Contrasting Color) | Parallel-Single Direction | Up to or equal to 8.3% |
| 2023314 | 314 | Point ZM | Missing (needed but does not exist) | <Null> | <Null> | Blended Transition | <Null> |
| 2023315 | 315 | Point ZM | Missing (needed but does not exist) | <Null> | <Null> | <Null> | <Null> |
| 2023316 | 316 | Point ZM | Missing (needed but does not exist) | <Null> | <Null> | Blended Transition | <Null> |
| 2023317 | 317 | Point ZM | Missing (needed but does not exist) | <Null> | <Null> | Blended Transition | <Null> |

City of Sultan
2023 ADA Access Plan GIS Curb Ramp Inventory

| TSI_Curb_Ramp_ID | OBJECTID * | SHAPE * | Condition * | Ramp_Width | DWS | Ramp_Type | Running_Slope |
|------------------|------------|----------|-------------------------------------|----------------|--|----------------------------------|------------------------|
| 2023318 | 318 | Point ZM | Missing (needed but does not exist) | <Null> | <Null> | Blended Transition | <Null> |
| 2023319 | 319 | Point ZM | Missing (needed but does not exist) | <Null> | <Null> | Blended Transition | <Null> |
| 2023320 | 320 | Point ZM | Missing (needed but does not exist) | <Null> | <Null> | Blended Transition | <Null> |
| 2023321 | 321 | Point ZM | Missing (needed but does not exist) | <Null> | <Null> | Blended Transition | <Null> |
| 2023322 | 322 | Point ZM | Missing (needed but does not exist) | <Null> | <Null> | Blended Transition | <Null> |
| 2023323 | 323 | Point ZM | Fair or Better | 48" or greater | Compliant (Truncated Domes with Contrasting Color) | Parallel-Single Direction | Up to or equal to 8.3% |
| 2023324 | 324 | Point ZM | Fair or Better | 48" or greater | Compliant (Truncated Domes with Contrasting Color) | Combination | Up to or equal to 8.3% |
| 2023325 | 325 | Point ZM | Fair or Better | 48" or greater | Compliant (Truncated Domes with Contrasting Color) | Parallel-Single Direction | Up to or equal to 8.3% |
| 2023326 | 326 | Point ZM | Fair or Better | 48" or greater | Compliant (Truncated Domes with Contrasting Color) | Parallel-Single Direction | Up to or equal to 8.3% |
| 2023327 | 599 | Point ZM | Poor | 36" to > 48" | Old Standard (Diamond/Exposed Aggregate) | Perpendicular (triangular wings) | Up to or equal to 8.3% |
| 2023328 | 598 | Point ZM | Missing (needed but does not exist) | <Null> | <Null> | <Null> | <Null> |
| 2023329 | 329 | Point ZM | Fair or Better | 48" or greater | Compliant (Truncated Domes with Contrasting Color) | Combination | Up to or equal to 8.3% |
| 2023330 | 330 | Point ZM | Missing (needed but does not exist) | <Null> | <Null> | <Null> | <Null> |
| 2023331 | 331 | Point ZM | Missing (needed but does not exist) | <Null> | <Null> | <Null> | <Null> |
| 2023332 | 332 | Point ZM | Missing (needed but does not exist) | 48" or greater | No DWS (Non-Compliant) | Blended Transition | <Null> |
| 2023333 | 333 | Point ZM | Missing (needed but does not exist) | <Null> | No DWS (Non-Compliant) | Blended Transition | <Null> |
| 2023334 | 334 | Point ZM | Fair or Better | 48" or greater | Compliant (Truncated Domes with Contrasting Color) | Combination | Up to or equal to 8.3% |
| 2023335 | 335 | Point ZM | Fair or Better | 48" or greater | Compliant (Truncated Domes with Contrasting Color) | Combination | Up to or equal to 8.3% |
| 2023336 | 336 | Point ZM | Fair or Better | 48" or greater | Compliant (Truncated Domes with Contrasting Color) | Blended Transition | Up to or equal to 8.3% |
| 2023337 | 337 | Point ZM | Fair or Better | 48" or greater | Compliant (Truncated Domes with Contrasting Color) | Blended Transition | Up to or equal to 8.3% |
| 2023338 | 338 | Point ZM | Fair or Better | 48" or greater | Compliant (Truncated Domes with Contrasting Color) | Unknown | Up to or equal to 8.3% |
| 2023339 | 339 | Point ZM | Fair or Better | 48" or greater | Compliant (Truncated Domes with Contrasting Color) | Parallel-Single Direction | Up to or equal to 8.3% |
| 2023340 | 340 | Point ZM | Fair or Better | 48" or greater | Compliant (Truncated Domes with Contrasting Color) | Parallel-Single Direction | Up to or equal to 8.3% |
| 2023341 | 341 | Point ZM | Fair or Better | 48" or greater | Compliant (Truncated Domes with Contrasting Color) | Parallel-Single Direction | Up to or equal to 8.3% |
| 2023342 | 342 | Point ZM | Fair or Better | 48" or greater | Compliant (Truncated Domes with Contrasting Color) | Blended Transition | Up to or equal to 8.3% |
| 2023343 | 343 | Point ZM | Fair or Better | 48" or greater | Compliant (Truncated Domes with Contrasting Color) | Blended Transition | Up to or equal to 8.3% |
| 2023344 | 344 | Point ZM | Fair or Better | 48" or greater | Compliant (Truncated Domes with Contrasting Color) | Combination | Up to or equal to 8.3% |
| 2023345 | 345 | Point ZM | Missing (needed but does not exist) | 48" or greater | No DWS (Non-Compliant) | Blended Transition | <Null> |
| 2023346 | 346 | Point ZM | Fair or Better | 48" or greater | Compliant (Truncated Domes with Contrasting Color) | Combination | Up to or equal to 8.3% |
| 2023347 | 347 | Point ZM | Fair or Better | 48" or greater | Compliant (Truncated Domes with Contrasting Color) | Combination | Up to or equal to 8.3% |
| 2023348 | 348 | Point ZM | Missing (needed but does not exist) | <Null> | <Null> | <Null> | <Null> |
| 2023349 | 349 | Point ZM | Missing (needed but does not exist) | <Null> | <Null> | <Null> | <Null> |
| 2023350 | 350 | Point ZM | Missing (needed but does not exist) | <Null> | <Null> | <Null> | <Null> |
| 2023351 | 351 | Point ZM | Fair or Better | 48" or greater | Compliant (Truncated Domes with Contrasting Color) | Combination | More than 8.3% |
| 2023352 | 352 | Point ZM | Fair or Better | 48" or greater | Compliant (Truncated Domes with Contrasting Color) | Combination | More than 8.3% |
| 2023353 | 353 | Point ZM | Missing (needed but does not exist) | <Null> | <Null> | <Null> | <Null> |
| 2023354 | 354 | Point ZM | Fair or Better | 48" or greater | Compliant (Truncated Domes with Contrasting Color) | Unknown | Up to or equal to 8.3% |
| 2023355 | 355 | Point ZM | Missing (needed but does not exist) | 48" or greater | No DWS (Non-Compliant) | <Null> | <Null> |
| 2023356 | 356 | Point ZM | Missing (needed but does not exist) | <Null> | <Null> | <Null> | <Null> |
| 2023357 | 357 | Point ZM | Fair or Better | 48" or greater | Compliant (Truncated Domes with Contrasting Color) | Perpendicular (triangular wings) | Up to or equal to 8.3% |
| 2023358 | 358 | Point ZM | Fair or Better | 48" or greater | Compliant (Truncated Domes with Contrasting Color) | Perpendicular (triangular wings) | Up to or equal to 8.3% |
| 2023359 | 359 | Point ZM | Fair or Better | 36" to > 48" | Compliant (Truncated Domes with Contrasting Color) | Perpendicular (triangular wings) | More than 8.3% |
| 2023360 | 360 | Point ZM | Fair or Better | 48" or greater | Compliant (Truncated Domes with Contrasting Color) | Perpendicular (triangular wings) | Up to or equal to 8.3% |
| 2023361 | 361 | Point ZM | Fair or Better | 36" to > 48" | Compliant (Truncated Domes with Contrasting Color) | Perpendicular (triangular wings) | More than 8.3% |

City of Sultan
2023 ADA Access Plan GIS Curb Ramp Inventory

| TSI_Curb_Ramp_ID | OBJECTID * | SHAPE * | Condition * | Ramp_Width | DWS | Ramp_Type | Running_Slope |
|------------------|------------|----------|-------------------------------------|----------------|--|----------------------------------|------------------------|
| 2023362 | 362 | Point ZM | Fair or Better | 48" or greater | Compliant (Truncated Domes with Contrasting Color) | Perpendicular (triangular wings) | Up to or equal to 8.3% |
| 2023363 | 363 | Point ZM | Missing (needed but does not exist) | <Null> | <Null> | <Null> | <Null> |
| 2023364 | 364 | Point ZM | Fair or Better | 48" or greater | Compliant (Truncated Domes with Contrasting Color) | Parallel-Single Direction | Up to or equal to 8.3% |
| 2023365 | 365 | Point ZM | Fair or Better | 48" or greater | Compliant (Truncated Domes with Contrasting Color) | Parallel-Single Direction | Up to or equal to 8.3% |
| 2023366 | 366 | Point ZM | Missing (needed but does not exist) | <Null> | <Null> | <Null> | <Null> |
| 2023367 | 367 | Point ZM | Fair or Better | 48" or greater | Compliant (Truncated Domes with Contrasting Color) | Parallel-Single Direction | <Null> |
| 2023368 | 368 | Point ZM | Missing (needed but does not exist) | <Null> | <Null> | <Null> | <Null> |
| 2023369 | 369 | Point ZM | Fair or Better | 48" or greater | Compliant (Truncated Domes with Contrasting Color) | Parallel-Single Direction | Up to or equal to 8.3% |
| 2023370 | 370 | Point ZM | Fair or Better | 48" or greater | Compliant (Truncated Domes with Contrasting Color) | Parallel-Single Direction | More than 8.3% |
| 2023371 | 371 | Point ZM | Fair or Better | 48" or greater | Compliant (Truncated Domes with Contrasting Color) | Parallel-Single Direction | Up to or equal to 8.3% |
| 2023372 | 372 | Point ZM | Fair or Better | 48" or greater | Compliant (Truncated Domes with Contrasting Color) | Parallel-Single Direction | Up to or equal to 8.3% |
| 2023373 | 373 | Point ZM | Fair or Better | 48" or greater | Compliant (Truncated Domes with Contrasting Color) | Parallel-Single Direction | Up to or equal to 8.3% |
| 2023374 | 374 | Point ZM | Fair or Better | 48" or greater | Compliant (Truncated Domes with Contrasting Color) | Parallel-Single Direction | Up to or equal to 8.3% |
| 2023375 | 375 | Point ZM | Fair or Better | 48" or greater | Compliant (Truncated Domes with Contrasting Color) | Parallel-Single Direction | Up to or equal to 8.3% |
| 2023376 | 376 | Point ZM | Fair or Better | 48" or greater | Compliant (Truncated Domes with Contrasting Color) | Perpendicular (triangular wings) | Up to or equal to 8.3% |
| 2023377 | 377 | Point ZM | Fair or Better | 48" or greater | Compliant (Truncated Domes with Contrasting Color) | Parallel-Single Direction | Up to or equal to 8.3% |
| 2023378 | 378 | Point ZM | Missing (needed but does not exist) | <Null> | <Null> | <Null> | <Null> |
| 2023379 | 379 | Point ZM | Missing (needed but does not exist) | <Null> | <Null> | <Null> | <Null> |
| 2023380 | 380 | Point ZM | Fair or Better | 36" to > 48" | Compliant (Truncated Domes with Contrasting Color) | Perpendicular (triangular wings) | More than 8.3% |
| 2023381 | 381 | Point ZM | Fair or Better | 36" to > 48" | Compliant (Truncated Domes with Contrasting Color) | Perpendicular (triangular wings) | More than 8.3% |
| 2023382 | 382 | Point ZM | Missing (needed but does not exist) | <Null> | <Null> | <Null> | <Null> |
| 2023383 | 383 | Point ZM | Fair or Better | 48" or greater | Compliant (Truncated Domes with Contrasting Color) | Perpendicular (triangular wings) | Up to or equal to 8.3% |
| 2023384 | 384 | Point ZM | Missing (needed but does not exist) | <Null> | <Null> | <Null> | <Null> |
| 2023385 | 385 | Point ZM | Missing (needed but does not exist) | <Null> | <Null> | <Null> | <Null> |
| 2023386 | 386 | Point ZM | Fair or Better | 48" or greater | Compliant (Truncated Domes with Contrasting Color) | Perpendicular (triangular wings) | More than 8.3% |
| 2023387 | 387 | Point ZM | Missing (needed but does not exist) | <Null> | <Null> | <Null> | <Null> |
| 2023388 | 388 | Point ZM | Missing (needed but does not exist) | <Null> | <Null> | <Null> | <Null> |
| 2023389 | 389 | Point ZM | Missing (needed but does not exist) | <Null> | <Null> | <Null> | <Null> |
| 2023390 | 390 | Point ZM | Fair or Better | 48" or greater | Compliant (Truncated Domes with Contrasting Color) | Perpendicular (triangular wings) | Up to or equal to 8.3% |
| 2023391 | 391 | Point ZM | Fair or Better | 48" or greater | Compliant (Truncated Domes with Contrasting Color) | Perpendicular (triangular wings) | Up to or equal to 8.3% |
| 2023392 | 392 | Point ZM | Fair or Better | 48" or greater | Compliant (Truncated Domes with Contrasting Color) | Perpendicular (triangular wings) | Up to or equal to 8.3% |
| 2023393 | 393 | Point ZM | Fair or Better | 48" or greater | Compliant (Truncated Domes with Contrasting Color) | Perpendicular (triangular wings) | Up to or equal to 8.3% |
| 2023394 | 394 | Point ZM | Poor | 48" or greater | Compliant (Truncated Domes with Contrasting Color) | Perpendicular (triangular wings) | Up to or equal to 8.3% |
| 2023395 | 395 | Point ZM | Missing (needed but does not exist) | <Null> | <Null> | <Null> | <Null> |
| 2023396 | 396 | Point ZM | Fair or Better | 48" or greater | Compliant (Truncated Domes with Contrasting Color) | Perpendicular (triangular wings) | Up to or equal to 8.3% |
| 2023397 | 397 | Point ZM | Fair or Better | 48" or greater | Compliant (Truncated Domes with Contrasting Color) | Perpendicular (triangular wings) | Up to or equal to 8.3% |
| 2023398 | 398 | Point ZM | Poor | 48" or greater | Compliant (Truncated Domes with Contrasting Color) | Perpendicular (triangular wings) | Up to or equal to 8.3% |
| 2023399 | 399 | Point ZM | Missing (needed but does not exist) | <Null> | No DWS (Non-Compliant) | <Null> | <Null> |
| 2023400 | 400 | Point ZM | Missing (needed but does not exist) | <Null> | <Null> | <Null> | <Null> |
| 2023401 | 401 | Point ZM | Missing (needed but does not exist) | <Null> | No DWS (Non-Compliant) | <Null> | <Null> |
| 2023402 | 402 | Point ZM | Missing (needed but does not exist) | <Null> | No DWS (Non-Compliant) | <Null> | <Null> |
| 2023403 | 403 | Point ZM | Missing (needed but does not exist) | <Null> | No DWS (Non-Compliant) | <Null> | <Null> |
| 2023404 | 404 | Point ZM | Missing (needed but does not exist) | <Null> | No DWS (Non-Compliant) | <Null> | <Null> |
| 2023405 | 405 | Point ZM | Fair or Better | 48" or greater | Compliant (Truncated Domes with Contrasting Color) | Parallel-Single Direction | Up to or equal to 8.3% |

City of Sultan
2023 ADA Access Plan GIS Curb Ramp Inventory

| TSI_Curb_Ramp_ID | OBJECTID * | SHAPE * | Condition * | Ramp_Width | DWS | Ramp_Type | Running_Slope |
|------------------|------------|----------|-------------------------------------|----------------|--|----------------------------------|------------------------|
| 2023452 | 452 | Point ZM | Fair or Better | 48" or greater | Compliant (Truncated Domes with Contrasting Color) | Parallel-Single Direction | Up to or equal to 8.3% |
| 2023453 | 453 | Point ZM | Fair or Better | 48" or greater | Compliant (Truncated Domes with Contrasting Color) | Parallel-Single Direction | Up to or equal to 8.3% |
| 2023454 | 454 | Point ZM | Fair or Better | 48" or greater | Compliant (Truncated Domes with Contrasting Color) | Parallel-Single Direction | Up to or equal to 8.3% |
| 2023455 | 455 | Point ZM | Fair or Better | 48" or greater | Compliant (Truncated Domes with Contrasting Color) | Parallel-Single Direction | Up to or equal to 8.3% |
| 2023456 | 456 | Point ZM | Fair or Better | 48" or greater | Compliant (Truncated Domes with Contrasting Color) | Parallel-Single Direction | Up to or equal to 8.3% |
| 2023457 | 457 | Point ZM | Fair or Better | 48" or greater | Compliant (Truncated Domes with Contrasting Color) | Parallel-Single Direction | Up to or equal to 8.3% |
| 2023458 | 458 | Point ZM | Fair or Better | 48" or greater | Compliant (Truncated Domes with Contrasting Color) | Parallel-Single Direction | Up to or equal to 8.3% |
| 2023459 | 459 | Point ZM | Fair or Better | 48" or greater | Compliant (Truncated Domes with Contrasting Color) | Parallel-Single Direction | Up to or equal to 8.3% |
| 2023460 | 460 | Point ZM | Fair or Better | <Null> | <Null> | <Null> | <Null> |
| 2023461 | 461 | Point ZM | Fair or Better | 48" or greater | Compliant (Truncated Domes with Contrasting Color) | Parallel-Single Direction | Up to or equal to 8.3% |
| 2023462 | 462 | Point ZM | Fair or Better | 48" or greater | Compliant (Truncated Domes with Contrasting Color) | Parallel-Single Direction | Up to or equal to 8.3% |
| 2023463 | 463 | Point ZM | Fair or Better | 48" or greater | Compliant (Truncated Domes with Contrasting Color) | Parallel-Diagonally Oriented | Up to or equal to 8.3% |
| 2023464 | 464 | Point ZM | Fair or Better | 48" or greater | Compliant (Truncated Domes with Contrasting Color) | Parallel-Single Direction | <Null> |
| 2023465 | 465 | Point ZM | Fair or Better | 48" or greater | Compliant (Truncated Domes with Contrasting Color) | Combination | Up to or equal to 8.3% |
| 2023466 | 466 | Point ZM | Fair or Better | 48" or greater | Compliant (Truncated Domes with Contrasting Color) | Parallel-Single Direction | Up to or equal to 8.3% |
| 2023467 | 467 | Point ZM | Fair or Better | 48" or greater | Compliant (Truncated Domes with Contrasting Color) | Parallel-Single Direction | Up to or equal to 8.3% |
| 2023468 | 468 | Point ZM | Fair or Better | 48" or greater | Compliant (Truncated Domes with Contrasting Color) | Parallel-Diagonally Oriented | Up to or equal to 8.3% |
| 2023469 | 469 | Point ZM | Fair or Better | 48" or greater | Compliant (Truncated Domes with Contrasting Color) | Parallel-Diagonally Oriented | Up to or equal to 8.3% |
| 2023470 | 470 | Point ZM | Fair or Better | 48" or greater | Compliant (Truncated Domes with Contrasting Color) | Parallel-Diagonally Oriented | Up to or equal to 8.3% |
| 2023471 | 471 | Point ZM | Very Poor | 48" or greater | No DWS (Non-Compliant) | Parallel-Single Direction | Up to or equal to 8.3% |
| 2023472 | 472 | Point ZM | Fair or Better | 48" or greater | Compliant (Truncated Domes with Contrasting Color) | Unknown | Up to or equal to 8.3% |
| 2023473 | 473 | Point ZM | Poor | 48" or greater | Compliant (Truncated Domes with Contrasting Color) | Combination | More than 8.3% |
| 2023474 | 474 | Point ZM | Missing (needed but does not exist) | 36" to > 48" | No DWS (Non-Compliant) | Unknown | <Null> |
| 2023475 | 475 | Point ZM | Poor | 36" to > 48" | Old Standard (Diamond/Exposed Aggregate) | Perpendicular (triangular wings) | Up to or equal to 8.3% |
| 2023476 | 476 | Point ZM | Poor | 36" to > 48" | Old Standard (Diamond/Exposed Aggregate) | Perpendicular (triangular wings) | Up to or equal to 8.3% |
| 2023477 | 477 | Point ZM | Missing (needed but does not exist) | <Null> | <Null> | <Null> | <Null> |
| 2023478 | 478 | Point ZM | Poor | 36" to > 48" | Old Standard (Diamond/Exposed Aggregate) | Perpendicular (triangular wings) | More than 8.3% |
| 2023479 | 479 | Point ZM | Missing (needed but does not exist) | <Null> | <Null> | Blended Transition | <Null> |
| 2023480 | 480 | Point ZM | Fair or Better | 48" or greater | Compliant (Truncated Domes with Contrasting Color) | Parallel-Single Direction | Up to or equal to 8.3% |
| 2023481 | 481 | Point ZM | Fair or Better | 48" or greater | Compliant (Truncated Domes with Contrasting Color) | Parallel-Single Direction | Up to or equal to 8.3% |
| 2023482 | 482 | Point ZM | Fair or Better | 48" or greater | Compliant (Truncated Domes with Contrasting Color) | Parallel-Single Direction | Up to or equal to 8.3% |
| 2023483 | 483 | Point ZM | Fair or Better | 48" or greater | Compliant (Truncated Domes with Contrasting Color) | Parallel-Single Direction | Up to or equal to 8.3% |
| 2023484 | 484 | Point ZM | Fair or Better | 48" or greater | Compliant (Truncated Domes with Contrasting Color) | Parallel-Single Direction | Up to or equal to 8.3% |
| 2023485 | 485 | Point ZM | Fair or Better | 48" or greater | Compliant (Truncated Domes with Contrasting Color) | Parallel-Single Direction | Up to or equal to 8.3% |
| 2023486 | 486 | Point ZM | Fair or Better | 48" or greater | Compliant (Truncated Domes with Contrasting Color) | Parallel-Single Direction | Up to or equal to 8.3% |
| 2023487 | 487 | Point ZM | Missing (needed but does not exist) | <Null> | <Null> | <Null> | <Null> |
| 2023488 | 488 | Point ZM | Fair or Better | 48" or greater | Compliant (Truncated Domes with Contrasting Color) | Parallel-Single Direction | Up to or equal to 8.3% |
| 2023489 | 489 | Point ZM | Fair or Better | 48" or greater | Compliant (Truncated Domes with Contrasting Color) | Parallel-Single Direction | Up to or equal to 8.3% |
| 2023490 | 490 | Point ZM | Fair or Better | 48" or greater | Compliant (Truncated Domes with Contrasting Color) | Parallel-Single Direction | Up to or equal to 8.3% |
| 2023491 | 491 | Point ZM | Missing (needed but does not exist) | <Null> | <Null> | <Null> | <Null> |
| 2023492 | 495 | Point ZM | Very Poor | Less than 36" | Old Standard (Diamond/Exposed Aggregate) | Perpendicular (triangular wings) | Up to or equal to 8.3% |
| 2023493 | 496 | Point ZM | Poor | 36" to > 48" | Old Standard (Diamond/Exposed Aggregate) | Perpendicular (triangular wings) | Up to or equal to 8.3% |
| 2023494 | 497 | Point ZM | Poor | 36" to > 48" | Old Standard (Diamond/Exposed Aggregate) | Perpendicular (triangular wings) | More than 8.3% |

City of Sultan
2023 ADA Access Plan GIS Curb Ramp Inventory

| TSI_Curb_Ramp_ID | OBJECTID * | SHAPE * | Condition * | Ramp_Width | DWS | Ramp_Type | Running_Slope |
|------------------|------------|----------|-------------------------------------|----------------|--|----------------------------------|------------------------|
| 2023495 | 498 | Point ZM | Poor | 36" to > 48" | Old Standard (Diamond/Exposed Aggregate) | Perpendicular (triangular wings) | More than 8.3% |
| 2023496 | 500 | Point ZM | Fair or Better | 48" or greater | Compliant (Truncated Domes with Contrasting Color) | Parallel-Single Direction | Up to or equal to 8.3% |
| 2023497 | 502 | Point ZM | Fair or Better | 48" or greater | Compliant (Truncated Domes with Contrasting Color) | Parallel-Single Direction | Up to or equal to 8.3% |
| 2023498 | 503 | Point ZM | Fair or Better | 48" or greater | Compliant (Truncated Domes with Contrasting Color) | Parallel-Single Direction | Up to or equal to 8.3% |
| 2023499 | 504 | Point ZM | Fair or Better | 48" or greater | Compliant (Truncated Domes with Contrasting Color) | Parallel-Single Direction | Up to or equal to 8.3% |
| 2023500 | 505 | Point ZM | Fair or Better | 48" or greater | Compliant (Truncated Domes with Contrasting Color) | Parallel-Single Direction | Up to or equal to 8.3% |
| 2023501 | 506 | Point ZM | Fair or Better | 48" or greater | Compliant (Truncated Domes with Contrasting Color) | Parallel-Single Direction | Up to or equal to 8.3% |
| 2023502 | 507 | Point ZM | Fair or Better | 48" or greater | Compliant (Truncated Domes with Contrasting Color) | Parallel-Single Direction | Up to or equal to 8.3% |
| 2023503 | 508 | Point ZM | Fair or Better | 48" or greater | Compliant (Truncated Domes with Contrasting Color) | Parallel-Single Direction | Up to or equal to 8.3% |
| 2023504 | 595 | Point ZM | Poor | 36" to > 48" | Old Standard (Diamond/Exposed Aggregate) | Perpendicular (triangular wings) | Up to or equal to 8.3% |
| 2023505 | 510 | Point ZM | Poor | 36" to > 48" | Old Standard (Diamond/Exposed Aggregate) | Perpendicular (triangular wings) | Up to or equal to 8.3% |
| 2023506 | 511 | Point ZM | Very Poor | 36" to > 48" | Old Standard (Diamond/Exposed Aggregate) | Perpendicular (triangular wings) | Up to or equal to 8.3% |
| 2023507 | 514 | Point ZM | Poor | 36" to > 48" | Old Standard (Diamond/Exposed Aggregate) | Perpendicular (triangular wings) | More than 8.3% |
| 2023508 | 515 | Point ZM | Poor | 36" to > 48" | Old Standard (Diamond/Exposed Aggregate) | Perpendicular (triangular wings) | Up to or equal to 8.3% |
| 2023509 | 516 | Point ZM | Poor | 36" to > 48" | Old Standard (Diamond/Exposed Aggregate) | Perpendicular (triangular wings) | More than 8.3% |
| 2023510 | 517 | Point ZM | Poor | 36" to > 48" | Old Standard (Diamond/Exposed Aggregate) | Perpendicular (triangular wings) | More than 8.3% |
| 2023511 | 518 | Point ZM | Poor | 36" to > 48" | Old Standard (Diamond/Exposed Aggregate) | Perpendicular (triangular wings) | More than 8.3% |
| 2023512 | 519 | Point ZM | Poor | 36" to > 48" | Old Standard (Diamond/Exposed Aggregate) | Perpendicular (triangular wings) | More than 8.3% |
| 2023513 | 521 | Point ZM | Missing (needed but does not exist) | <Null> | <Null> | <Null> | <Null> |
| 2023514 | 522 | Point ZM | Poor | 36" to > 48" | Old Standard (Diamond/Exposed Aggregate) | Perpendicular (triangular wings) | More than 8.3% |
| 2023515 | 523 | Point ZM | Poor | 36" to > 48" | Old Standard (Diamond/Exposed Aggregate) | Perpendicular (triangular wings) | More than 8.3% |
| 2023516 | 524 | Point ZM | Poor | 36" to > 48" | Old Standard (Diamond/Exposed Aggregate) | Perpendicular (triangular wings) | More than 8.3% |
| 2023517 | 525 | Point ZM | Poor | 36" to > 48" | Old Standard (Diamond/Exposed Aggregate) | Perpendicular (triangular wings) | More than 8.3% |
| 2023518 | 526 | Point ZM | Poor | 36" to > 48" | Old Standard (Diamond/Exposed Aggregate) | Perpendicular (triangular wings) | More than 8.3% |
| 2023519 | 527 | Point ZM | Poor | 36" to > 48" | Old Standard (Diamond/Exposed Aggregate) | Perpendicular (triangular wings) | More than 8.3% |
| 2023520 | 528 | Point ZM | Very Poor | 36" to > 48" | Old Standard (Diamond/Exposed Aggregate) | Perpendicular (triangular wings) | More than 8.3% |
| 2023521 | 529 | Point ZM | Poor | 36" to > 48" | Old Standard (Diamond/Exposed Aggregate) | Perpendicular (triangular wings) | More than 8.3% |
| 2023522 | 530 | Point ZM | Fair or Better | 48" or greater | Compliant (Truncated Domes with Contrasting Color) | Parallel-Single Direction | More than 8.3% |
| 2023523 | 531 | Point ZM | Fair or Better | 48" or greater | Compliant (Truncated Domes with Contrasting Color) | Parallel-Single Direction | More than 8.3% |
| 2023524 | 532 | Point ZM | Fair or Better | 48" or greater | Compliant (Truncated Domes with Contrasting Color) | Parallel-Single Direction | More than 8.3% |
| 2023525 | 533 | Point ZM | Fair or Better | 48" or greater | Compliant (Truncated Domes with Contrasting Color) | Parallel-Single Direction | Up to or equal to 8.3% |
| 2023526 | 534 | Point ZM | Fair or Better | 48" or greater | Compliant (Truncated Domes with Contrasting Color) | Parallel-Single Direction | More than 8.3% |
| 2023527 | 535 | Point ZM | Fair or Better | 48" or greater | Compliant (Truncated Domes with Contrasting Color) | Parallel-Single Direction | More than 8.3% |
| 2023528 | 540 | Point ZM | Poor | 36" to > 48" | Old Standard (Diamond/Exposed Aggregate) | Perpendicular (triangular wings) | More than 8.3% |
| 2023529 | 541 | Point ZM | Poor | 36" to > 48" | Old Standard (Diamond/Exposed Aggregate) | Perpendicular (triangular wings) | More than 8.3% |
| 2023530 | 543 | Point ZM | Poor | 36" to > 48" | Old Standard (Diamond/Exposed Aggregate) | Perpendicular (triangular wings) | More than 8.3% |
| 2023531 | 544 | Point ZM | Poor | 36" to > 48" | Old Standard (Diamond/Exposed Aggregate) | Perpendicular (triangular wings) | More than 8.3% |
| 2023532 | 545 | Point ZM | Very Poor | Less than 36" | Old Standard (Diamond/Exposed Aggregate) | Unknown | More than 8.3% |
| 2023533 | 546 | Point ZM | Fair or Better | 48" or greater | Compliant (Truncated Domes with Contrasting Color) | Parallel-Single Direction | Up to or equal to 8.3% |
| 2023534 | 547 | Point ZM | Poor | 48" or greater | Compliant (Truncated Domes with Contrasting Color) | Unknown | Up to or equal to 8.3% |
| 2023535 | 548 | Point ZM | Poor | 48" or greater | Compliant (Truncated Domes with Contrasting Color) | Unknown | Up to or equal to 8.3% |
| 2023536 | 549 | Point ZM | Fair or Better | 48" or greater | Compliant (Truncated Domes with Contrasting Color) | Parallel-Single Direction | Up to or equal to 8.3% |
| 2023537 | 550 | Point ZM | Fair or Better | 48" or greater | Compliant (Truncated Domes with Contrasting Color) | Parallel-Single Direction | Up to or equal to 8.3% |

City of Sultan
2023 ADA Access Plan GIS Curb Ramp Inventory

| TSI_Curb_Ramp_ID | OBJECTID * | SHAPE * | Condition * | Ramp_Width | DWS | Ramp_Type | Running_Slope |
|------------------|------------|----------|-------------------------------------|----------------|--|----------------------------------|------------------------|
| 2023538 | 551 | Point ZM | Fair or Better | 48" or greater | Compliant (Truncated Domes with Contrasting Color) | Parallel-Single Direction | Up to or equal to 8.3% |
| 2023539 | 552 | Point ZM | Fair or Better | 48" or greater | Compliant (Truncated Domes with Contrasting Color) | <Null> | Up to or equal to 8.3% |
| 2023540 | 553 | Point ZM | Very Poor | 48" or greater | No DWS (Non-Compliant) | Blended Transition | Up to or equal to 8.3% |
| 2023541 | 554 | Point ZM | Very Poor | 48" or greater | No DWS (Non-Compliant) | Blended Transition | Up to or equal to 8.3% |
| 2023542 | 555 | Point ZM | Very Poor | 48" or greater | No DWS (Non-Compliant) | Parallel-Single Direction | Up to or equal to 8.3% |
| 2023543 | 556 | Point ZM | Very Poor | 48" or greater | No DWS (Non-Compliant) | Parallel-Single Direction | Up to or equal to 8.3% |
| 2023544 | 557 | Point ZM | Missing (needed but does not exist) | 48" or greater | No DWS (Non-Compliant) | Parallel-Single Direction | <Null> |
| 2023545 | 558 | Point ZM | Missing (needed but does not exist) | <Null> | <Null> | <Null> | <Null> |
| 2023546 | 559 | Point ZM | Missing (needed but does not exist) | <Null> | <Null> | <Null> | <Null> |
| 2023547 | 560 | Point ZM | Missing (needed but does not exist) | <Null> | No DWS (Non-Compliant) | Blended Transition | <Null> |
| 2023548 | 561 | Point ZM | Very Poor | 48" or greater | No DWS (Non-Compliant) | Unknown | More than 8.3% |
| 2023549 | 562 | Point ZM | Poor | 36" to > 48" | Old Standard (Diamond/Exposed Aggregate) | Perpendicular (triangular wings) | More than 8.3% |
| 2023550 | 563 | Point ZM | Poor | 36" to > 48" | Old Standard (Diamond/Exposed Aggregate) | Perpendicular (triangular wings) | Up to or equal to 8.3% |
| 2023551 | 564 | Point ZM | Missing (needed but does not exist) | <Null> | <Null> | <Null> | <Null> |
| 2023552 | 565 | Point ZM | Very Poor | <Null> | <Null> | <Null> | <Null> |
| 2023553 | 566 | Point ZM | Very Poor | <Null> | <Null> | <Null> | <Null> |
| 2023554 | 568 | Point ZM | Missing (needed but does not exist) | <Null> | <Null> | <Null> | <Null> |
| 2023555 | 569 | Point ZM | Missing (needed but does not exist) | <Null> | <Null> | <Null> | <Null> |
| 2023556 | 572 | Point ZM | Poor | 48" or greater | Compliant (Truncated Domes with Contrasting Color) | Perpendicular (triangular wings) | Up to or equal to 8.3% |
| 2023557 | 573 | Point ZM | Poor | 48" or greater | Compliant (Truncated Domes with Contrasting Color) | Perpendicular (triangular wings) | More than 8.3% |
| 2023558 | 574 | Point ZM | Missing (needed but does not exist) | <Null> | <Null> | <Null> | <Null> |
| 2023559 | 575 | Point ZM | Fair or Better | 48" or greater | Compliant (Truncated Domes with Contrasting Color) | Parallel-Single Direction | Up to or equal to 8.3% |
| 2023560 | 576 | Point ZM | Fair or Better | 48" or greater | Compliant (Truncated Domes with Contrasting Color) | Parallel-Single Direction | Up to or equal to 8.3% |
| 2023561 | 579 | Point ZM | Fair or Better | 48" or greater | Compliant (Truncated Domes with Contrasting Color) | Parallel-Single Direction | Up to or equal to 8.3% |
| 2023562 | 580 | Point ZM | Fair or Better | 48" or greater | Compliant (Truncated Domes with Contrasting Color) | Perpendicular (triangular wings) | Up to or equal to 8.3% |
| 2023563 | 581 | Point ZM | Fair or Better | 48" or greater | Compliant (Truncated Domes with Contrasting Color) | Combination | Up to or equal to 8.3% |
| 2023564 | 582 | Point ZM | Very Poor | 48" or greater | Old Standard (Diamond/Exposed Aggregate) | Unknown | More than 8.3% |
| 2023565 | 583 | Point ZM | Fair or Better | 48" or greater | Compliant (Truncated Domes with Contrasting Color) | Parallel-Single Direction | Up to or equal to 8.3% |
| 2023566 | 584 | Point ZM | Fair or Better | 48" or greater | Compliant (Truncated Domes with Contrasting Color) | Parallel-Single Direction | Up to or equal to 8.3% |
| 2023567 | 492 | Point ZM | Missing (needed but does not exist) | <Null> | No DWS (Non-Compliant) | <Null> | <Null> |
| 2023568 | 493 | Point ZM | Missing (needed but does not exist) | <Null> | No DWS (Non-Compliant) | <Null> | <Null> |
| 2023569 | 494 | Point ZM | Missing (needed but does not exist) | 36" to > 48" | No DWS (Non-Compliant) | Blended Transition | More than 8.3% |
| 2023570 | 499 | Point ZM | Missing (needed but does not exist) | <Null> | <Null> | <Null> | <Null> |
| 2023571 | 501 | Point ZM | Missing (needed but does not exist) | <Null> | <Null> | <Null> | <Null> |
| 2023572 | 512 | Point ZM | Missing (needed but does not exist) | <Null> | <Null> | <Null> | <Null> |
| 2023573 | 513 | Point ZM | Missing (needed but does not exist) | <Null> | <Null> | <Null> | <Null> |
| 2023574 | 520 | Point ZM | Missing (needed but does not exist) | <Null> | <Null> | <Null> | <Null> |
| 2023575 | 536 | Point ZM | Missing (needed but does not exist) | <Null> | <Null> | <Null> | <Null> |
| 2023576 | 537 | Point ZM | Missing (needed but does not exist) | <Null> | <Null> | <Null> | <Null> |
| 2023577 | 538 | Point ZM | Missing (needed but does not exist) | <Null> | <Null> | <Null> | <Null> |
| 2023578 | 539 | Point ZM | Missing (needed but does not exist) | <Null> | <Null> | <Null> | <Null> |
| 2023579 | 542 | Point ZM | Missing (needed but does not exist) | <Null> | No DWS (Non-Compliant) | <Null> | <Null> |
| 2023580 | 567 | Point ZM | Missing (needed but does not exist) | <Null> | <Null> | <Null> | <Null> |
| 2023581 | 570 | Point ZM | Missing (needed but does not exist) | <Null> | <Null> | <Null> | <Null> |
| 2023582 | 571 | Point ZM | Missing (needed but does not exist) | <Null> | <Null> | <Null> | <Null> |
| 2023583 | 577 | Point ZM | Missing (needed but does not exist) | <Null> | <Null> | <Null> | <Null> |

City of Sultan
2023 ADA Access Plan GIS Curb Ramp Inventory

| TSI_Curb_Ramp_ID | OBJECTID * | SHAPE * | Condition * | Ramp_Width | DWS | Ramp_Type | Running_Slope |
|------------------|------------|----------|-------------------------------------|----------------|--|----------------------------------|------------------------|
| 2023584 | 578 | Point ZM | Missing (needed but does not exist) | <Null> | <Null> | <Null> | <Null> |
| 2023585 | 587 | Point ZM | Missing (needed but does not exist) | <Null> | No DWS (Non-Compliant) | <Null> | <Null> |
| 2023586 | 589 | Point ZM | Missing (needed but does not exist) | <Null> | <Null> | <Null> | <Null> |
| 2023587 | 585 | Point ZM | Fair or Better | 48" or greater | Compliant (Truncated Domes with Contrasting Color) | Perpendicular (triangular wings) | Up to or equal to 8.3% |
| 2023588 | 586 | Point ZM | Poor | 36" to > 48" | Old Standard (Diamond/Exposed Aggregate) | Perpendicular (triangular wings) | More than 8.3% |
| 2023589 | 588 | Point ZM | Poor | 36" to > 48" | Old Standard (Diamond/Exposed Aggregate) | Perpendicular (triangular wings) | More than 8.3% |
| 2023590 | 590 | Point ZM | Very Poor | Less than 36" | Compliant (Truncated Domes with Contrasting Color) | Perpendicular (triangular wings) | More than 8.3% |
| 2023591 | 591 | Point ZM | Very Poor | 48" or greater | No DWS (Non-Compliant) | Unknown | More than 8.3% |
| 2023592 | 592 | Point ZM | Very Poor | Less than 36" | Compliant (Truncated Domes with Contrasting Color) | Perpendicular (triangular wings) | More than 8.3% |
| 2023593 | 593 | Point ZM | Poor | 48" or greater | Old Standard (Diamond/Exposed Aggregate) | Perpendicular (triangular wings) | Up to or equal to 8.3% |
| 2023594 | 594 | Point ZM | Poor | 36" to > 48" | Old Standard (Diamond/Exposed Aggregate) | Perpendicular (triangular wings) | More than 8.3% |
| 2023595 | 604 | Point ZM | Fair or Better | 48" or greater | Compliant (Truncated Domes with Contrasting Color) | Blended Transition | Up to or equal to 8.3% |

City of Sultan
2023 ADA Access Plan GIS Curb Ramp Inventory

| TSI_Curb_Ramp_ID | Cross_Slope | Landing | Grade * | Notes | ADA_Compliance |
|------------------|----------------------|-----------------------|---------|---------------------------------------|----------------|
| 2023001 | Up to or equal to 2% | 4 x 4 feet or greater | A | Sand debri | Yes |
| 2023002 | Up to or equal to 2% | 4 x 4 feet or greater | A | DWS color contrast faded | No |
| 2023003 | Up to or equal to 2% | 4 x 4 feet or greater | A | <Null> | Yes |
| 2023004 | Up to or equal to 2% | 4 x 4 feet or greater | A | <Null> | Yes |
| 2023005 | Up to or equal to 2% | 4 x 4 feet or greater | A | <Null> | Yes |
| 2023006 | Up to or equal to 2% | 4 x 4 feet or greater | A | <Null> | Yes |
| 2023007 | Up to or equal to 2% | Less than 4 x 4 feet | B | Landing obstructed by second curb | No |
| 2023008 | Up to or equal to 2% | 4 x 4 feet or greater | A | <Null> | Yes |
| 2023009 | Up to or equal to 2% | 4 x 4 feet or greater | A | <Null> | Yes |
| 2023010 | Up to or equal to 2% | 4 x 4 feet or greater | A | <Null> | Yes |
| 2023011 | Up to or equal to 2% | 4 x 4 feet or greater | A | <Null> | Yes |
| 2023012 | Up to or equal to 2% | 4 x 4 feet or greater | A | <Null> | Yes |
| 2023013 | Up to or equal to 2% | 4 x 4 feet or greater | A | <Null> | Yes |
| 2023014 | Up to or equal to 2% | 4 x 4 feet or greater | A | <Null> | Yes |
| 2023015 | More than 2% | 4 x 4 feet or greater | D | DWS recommended for consistency | No |
| 2023016 | Up to or equal to 2% | Less than 4 x 4 feet | D | DWS recommended for consistency | No |
| 2023017 | Up to or equal to 2% | 4 x 4 feet or greater | A | <Null> | Yes |
| 2023018 | Up to or equal to 2% | 4 x 4 feet or greater | A | <Null> | Yes |
| 2023019 | Up to or equal to 2% | 4 x 4 feet or greater | A | Landing slope 2.3% | No |
| 2023020 | Up to or equal to 2% | 4 x 4 feet or greater | A | <Null> | Yes |
| 2023021 | Up to or equal to 2% | 4 x 4 feet or greater | A | <Null> | Yes |
| 2023022 | Up to or equal to 2% | 4 x 4 feet or greater | A | <Null> | Yes |
| 2023023 | Up to or equal to 2% | 4 x 4 feet or greater | A | Concrete planter within landing | Yes |
| 2023024 | Up to or equal to 2% | 4 x 4 feet or greater | A | <Null> | Yes |
| 2023025 | Up to or equal to 2% | 4 x 4 feet or greater | A | <Null> | Yes |
| 2023026 | Up to or equal to 2% | 4 x 4 feet or greater | A | <Null> | Yes |
| 2023027 | Up to or equal to 2% | 4 x 4 feet or greater | A | <Null> | Yes |
| 2023028 | Up to or equal to 2% | 4 x 4 feet or greater | A | <Null> | Yes |
| 2023029 | Up to or equal to 2% | 4 x 4 feet or greater | A | <Null> | Yes |
| 2023030 | Up to or equal to 2% | 4 x 4 feet or greater | A | <Null> | Yes |
| 2023031 | Up to or equal to 2% | 4 x 4 feet or greater | A | <Null> | Yes |
| 2023032 | Up to or equal to 2% | 4 x 4 feet or greater | A | <Null> | Yes |
| 2023033 | Up to or equal to 2% | 4 x 4 feet or greater | A | <Null> | Yes |
| 2023034 | Up to or equal to 2% | 4 x 4 feet or greater | A | <Null> | Yes |
| 2023035 | Up to or equal to 2% | 4 x 4 feet or greater | A | <Null> | Yes |
| 2023036 | Up to or equal to 2% | 4 x 4 feet or greater | A | <Null> | Yes |
| 2023037 | Up to or equal to 2% | 4 x 4 feet or greater | A | <Null> | Yes |
| 2023038 | Up to or equal to 2% | 4 x 4 feet or greater | A | <Null> | Yes |
| 2023039 | Up to or equal to 2% | 4 x 4 feet or greater | C | Broken flare corner | No |
| 2023040 | Up to or equal to 2% | 4 x 4 feet or greater | A | <Null> | Yes |
| 2023041 | Up to or equal to 2% | 4 x 4 feet or greater | A | <Null> | Yes |
| 2023042 | Up to or equal to 2% | 4 x 4 feet or greater | A | <Null> | Yes |
| 2023043 | Up to or equal to 2% | 4 x 4 feet or greater | A | <Null> | Yes |
| 2023044 | Up to or equal to 2% | 4 x 4 feet or greater | A | NW approach running slope exceeds 10% | Yes |
| 2023045 | Up to or equal to 2% | 4 x 4 feet or greater | A | <Null> | Yes |
| 2023046 | Up to or equal to 2% | 4 x 4 feet or greater | A | NW running slope 8.7% | Yes |

City of Sultan
2023 ADA Access Plan GIS Curb Ramp Inventory

| TSI_Curb_Ramp_ID | Cross_Slope | Landing | Grade * | Notes | ADA_Compliance |
|------------------|----------------------|-----------------------|---------|---|----------------|
| 2023047 | Up to or equal to 2% | Less than 4 x 4 feet | C | Driveway servicing pedestrian crossing with lip | No |
| 2023048 | Up to or equal to 2% | 4 x 4 feet or greater | C | Mid street refuge | No |
| 2023049 | Up to or equal to 2% | Less than 4 x 4 feet | C | PAR cross slope 8% | No |
| 2023050 | Up to or equal to 2% | 4 x 4 feet or greater | A | <Null> | Yes |
| 2023051 | Up to or equal to 2% | 4 x 4 feet or greater | A | <Null> | Yes |
| 2023052 | Up to or equal to 2% | 4 x 4 feet or greater | A | <Null> | Yes |
| 2023053 | Up to or equal to 2% | 4 x 4 feet or greater | A | <Null> | Yes |
| 2023054 | Up to or equal to 2% | 4 x 4 feet or greater | A | <Null> | Yes |
| 2023055 | Up to or equal to 2% | 4 x 4 feet or greater | A | <Null> | Yes |
| 2023056 | Up to or equal to 2% | 4 x 4 feet or greater | A | <Null> | Yes |
| 2023057 | Up to or equal to 2% | 4 x 4 feet or greater | A | <Null> | Yes |
| 2023058 | Up to or equal to 2% | 4 x 4 feet or greater | A | <Null> | Yes |
| 2023059 | Up to or equal to 2% | 4 x 4 feet or greater | A | <Null> | Yes |
| 2023060 | Up to or equal to 2% | 4 x 4 feet or greater | A | <Null> | Yes |
| 2023061 | Up to or equal to 2% | 4 x 4 feet or greater | A | <Null> | Yes |
| 2023062 | Up to or equal to 2% | 4 x 4 feet or greater | A | <Null> | Yes |
| 2023063 | Up to or equal to 2% | 4 x 4 feet or greater | A | <Null> | Yes |
| 2023064 | Up to or equal to 2% | 4 x 4 feet or greater | A | <Null> | Yes |
| 2023065 | Up to or equal to 2% | 4 x 4 feet or greater | A | <Null> | Yes |
| 2023066 | Up to or equal to 2% | 4 x 4 feet or greater | A | <Null> | Yes |
| 2023067 | Up to or equal to 2% | 4 x 4 feet or greater | A | <Null> | Yes |
| 2023068 | Up to or equal to 2% | 4 x 4 feet or greater | A | <Null> | Yes |
| 2023069 | Up to or equal to 2% | 4 x 4 feet or greater | A | <Null> | Yes |
| 2023070 | Up to or equal to 2% | 4 x 4 feet or greater | A | <Null> | Yes |
| 2023071 | Up to or equal to 2% | 4 x 4 feet or greater | A | <Null> | Yes |
| 2023072 | Up to or equal to 2% | 4 x 4 feet or greater | A | <Null> | Yes |
| 2023073 | Up to or equal to 2% | 4 x 4 feet or greater | A | <Null> | Yes |
| 2023074 | Up to or equal to 2% | 4 x 4 feet or greater | A | <Null> | Yes |
| 2023075 | Up to or equal to 2% | 4 x 4 feet or greater | A | <Null> | Yes |
| 2023076 | Up to or equal to 2% | 4 x 4 feet or greater | A | <Null> | Yes |
| 2023077 | Up to or equal to 2% | 4 x 4 feet or greater | A | <Null> | Yes |
| 2023078 | Up to or equal to 2% | 4 x 4 feet or greater | A | <Null> | Yes |
| 2023079 | Up to or equal to 2% | 4 x 4 feet or greater | A | <Null> | Yes |
| 2023080 | Up to or equal to 2% | 4 x 4 feet or greater | A | <Null> | Yes |
| 2023081 | Up to or equal to 2% | 4 x 4 feet or greater | C | Running slope 9.3% | No |
| 2023082 | Up to or equal to 2% | 4 x 4 feet or greater | C | <Null> | No |
| 2023083 | Up to or equal to 2% | 4 x 4 feet or greater | C | Lip on curb ramp | No |
| 2023084 | Up to or equal to 2% | 4 x 4 feet or greater | C | <Null> | No |
| 2023085 | Up to or equal to 2% | 4 x 4 feet or greater | C | Curb ramp lip | No |
| 2023086 | Up to or equal to 2% | 4 x 4 feet or greater | A | Running slope 9%. DWS deterioration. | No |
| 2023087 | Up to or equal to 2% | 4 x 4 feet or greater | A | DWS deterioration | No |
| 2023088 | Up to or equal to 2% | 4 x 4 feet or greater | B | Running slope 9%. DWS color deterioration. | No |
| 2023089 | Up to or equal to 2% | 4 x 4 feet or greater | B | DWS color deterioration | No |
| 2023090 | More than 2% | 4 x 4 feet or greater | B | Overgrown vegetation. | No |
| 2023091 | Up to or equal to 2% | 4 x 4 feet or greater | C | Running slope 11%. Cracks in flares. | No |
| 2023092 | Up to or equal to 2% | 4 x 4 feet or greater | B | Overgrown vegetation. Curb lip. | No |

City of Sultan
2023 ADA Access Plan GIS Curb Ramp Inventory

| TSI_Curb_Ramp_ID | Cross_Slope | Landing | Grade * | Notes | ADA_Compliance |
|------------------|----------------------|-----------------------|---------|---|----------------|
| 2023093 | Up to or equal to 2% | 4 x 4 feet or greater | A | <Null> | Yes |
| 2023094 | Up to or equal to 2% | 4 x 4 feet or greater | A | <Null> | Yes |
| 2023095 | Up to or equal to 2% | 4 x 4 feet or greater | B | Overgrown vegetation. Curb lip. | No |
| 2023096 | Up to or equal to 2% | 4 x 4 feet or greater | A | <Null> | Yes |
| 2023097 | Up to or equal to 2% | 4 x 4 feet or greater | A | <Null> | Yes |
| 2023098 | Up to or equal to 2% | 4 x 4 feet or greater | A | <Null> | Yes |
| 2023099 | Up to or equal to 2% | 4 x 4 feet or greater | A | Overgrown vegetation. | No |
| 2023100 | Up to or equal to 2% | 4 x 4 feet or greater | A | <Null> | Yes |
| 2023101 | Up to or equal to 2% | 4 x 4 feet or greater | A | <Null> | Yes |
| 2023102 | Up to or equal to 2% | 4 x 4 feet or greater | A | <Null> | Yes |
| 2023103 | Up to or equal to 2% | 4 x 4 feet or greater | A | <Null> | Yes |
| 2023104 | Up to or equal to 2% | 4 x 4 feet or greater | A | <Null> | Yes |
| 2023105 | Up to or equal to 2% | 4 x 4 feet or greater | A | <Null> | Yes |
| 2023106 | Up to or equal to 2% | 4 x 4 feet or greater | A | <Null> | Yes |
| 2023107 | Up to or equal to 2% | 4 x 4 feet or greater | A | <Null> | Yes |
| 2023108 | Up to or equal to 2% | 4 x 4 feet or greater | A | <Null> | Yes |
| 2023109 | Up to or equal to 2% | 4 x 4 feet or greater | A | <Null> | Yes |
| 2023110 | Up to or equal to 2% | 4 x 4 feet or greater | A | <Null> | Yes |
| 2023111 | Up to or equal to 2% | 4 x 4 feet or greater | A | <Null> | Yes |
| 2023112 | Up to or equal to 2% | 4 x 4 feet or greater | A | <Null> | Yes |
| 2023113 | Up to or equal to 2% | 4 x 4 feet or greater | A | <Null> | Yes |
| 2023114 | Up to or equal to 2% | 4 x 4 feet or greater | A | <Null> | Yes |
| 2023115 | Up to or equal to 2% | 4 x 4 feet or greater | A | <Null> | Yes |
| 2023116 | Up to or equal to 2% | 4 x 4 feet or greater | A | <Null> | Yes |
| 2023117 | Up to or equal to 2% | 4 x 4 feet or greater | A | <Null> | Yes |
| 2023118 | Up to or equal to 2% | 4 x 4 feet or greater | A | <Null> | Yes |
| 2023119 | Up to or equal to 2% | 4 x 4 feet or greater | A | <Null> | Yes |
| 2023120 | Up to or equal to 2% | 4 x 4 feet or greater | A | <Null> | Yes |
| 2023121 | Up to or equal to 2% | 4 x 4 feet or greater | A | <Null> | Yes |
| 2023122 | Up to or equal to 2% | 4 x 4 feet or greater | A | <Null> | Yes |
| 2023123 | Up to or equal to 2% | 4 x 4 feet or greater | A | <Null> | Yes |
| 2023124 | Up to or equal to 2% | 4 x 4 feet or greater | A | <Null> | Yes |
| 2023125 | Up to or equal to 2% | 4 x 4 feet or greater | A | <Null> | Yes |
| 2023126 | Up to or equal to 2% | 4 x 4 feet or greater | A | <Null> | Yes |
| 2023127 | Up to or equal to 2% | 4 x 4 feet or greater | A | <Null> | Yes |
| 2023128 | Up to or equal to 2% | 4 x 4 feet or greater | A | <Null> | Yes |
| 2023129 | Up to or equal to 2% | 4 x 4 feet or greater | B | Curb lip. | No |
| 2023130 | More than 2% | Less than 4 x 4 feet | B | Cross slope 3%. Landing cross slope 4%. Curb lip. | No |
| 2023131 | Up to or equal to 2% | 4 x 4 feet or greater | B | PAR cross slope 2.5%. Overgrown vegetation. Curb lip. | No |
| 2023132 | Up to or equal to 2% | 4 x 4 feet or greater | B | PAR cross slope 2.3%. Curb lip. | No |
| 2023133 | Up to or equal to 2% | Less than 4 x 4 feet | B | Overgrown vegetation. Curb lip. | No |
| 2023134 | Up to or equal to 2% | Less than 4 x 4 feet | B | Running slope 12%. Curb lip. | No |
| 2023135 | Up to or equal to 2% | 4 x 4 feet or greater | B | Curb lip. | No |
| 2023136 | Up to or equal to 2% | Less than 4 x 4 feet | C | PAR cross slope 4%. Cracks in landing area. Debris. | No |
| 2023137 | Up to or equal to 2% | Less than 4 x 4 feet | B | <Null> | No |
| 2023138 | Up to or equal to 2% | 4 x 4 feet or greater | C | Running slope 13% | No |

City of Sultan
2023 ADA Access Plan GIS Curb Ramp Inventory

| TSI_Curb_Ramp_ID | Cross_Slope | Landing | Grade * | Notes | ADA_Compliance |
|------------------|----------------------|-----------------------|---------|--|----------------|
| 2023139 | Up to or equal to 2% | 4 x 4 feet or greater | C | Running slope 15% | No |
| 2023140 | Up to or equal to 2% | Less than 4 x 4 feet | C | Running slope 10%. | No |
| 2023141 | Up to or equal to 2% | 4 x 4 feet or greater | B | Gravel debris. DWS color deterioration. | No |
| 2023142 | <Null> | <Null> | D | No receiving ramp at intersection | No |
| 2023143 | Up to or equal to 2% | 4 x 4 feet or greater | B | Running slope 11%. | No |
| 2023144 | Up to or equal to 2% | Less than 4 x 4 feet | C | <Null> | No |
| 2023145 | Up to or equal to 2% | 4 x 4 feet or greater | A | <Null> | Yes |
| 2023146 | <Null> | <Null> | D | <Null> | No |
| 2023147 | <Null> | <Null> | D | <Null> | No |
| 2023148 | <Null> | <Null> | D | Extend sidewalk to curb and provide ramp | No |
| 2023149 | <Null> | <Null> | D | Extend sidewalk to curb and provide ramp | No |
| 2023150 | <Null> | <Null> | D | Extend sidewalk to curb and provide ramp | No |
| 2023151 | <Null> | <Null> | D | Extend sidewalk to curb and provide ramp | No |
| 2023152 | Up to or equal to 2% | 4 x 4 feet or greater | A | <Null> | Yes |
| 2023153 | Up to or equal to 2% | 4 x 4 feet or greater | A | Debris | Yes |
| 2023154 | Up to or equal to 2% | 4 x 4 feet or greater | A | <Null> | Yes |
| 2023155 | Up to or equal to 2% | 4 x 4 feet or greater | A | <Null> | Yes |
| 2023156 | Up to or equal to 2% | 4 x 4 feet or greater | A | <Null> | Yes |
| 2023157 | Up to or equal to 2% | 4 x 4 feet or greater | A | <Null> | Yes |
| 2023158 | Up to or equal to 2% | 4 x 4 feet or greater | A | <Null> | Yes |
| 2023159 | More than 2% | 4 x 4 feet or greater | B | Minor curb lip. Running slope 10%. Cross slope 3%. | No |
| 2023160 | Up to or equal to 2% | 4 x 4 feet or greater | B | Minor curb lip. | No |
| 2023161 | Up to or equal to 2% | Less than 4 x 4 feet | C | Minor curb lip. Insufficient landing clear space. | No |
| 2023162 | Up to or equal to 2% | 4 x 4 feet or greater | C | Minor curb lip. Cracks forming within ramp. | No |
| 2023163 | Up to or equal to 2% | Less than 4 x 4 feet | C | No Landing. Running slope 10%. Steep flare slopes. | No |
| 2023164 | <Null> | <Null> | D | No receiving ramp at marked pedestrian crossing | No |
| 2023165 | Up to or equal to 2% | 4 x 4 feet or greater | B | Minor curb lip. Adjacent PAR less than 4 feet wide. | No |
| 2023166 | Up to or equal to 2% | Less than 4 x 4 feet | C | No Landing. Running slope 10% minor curb lip. | No |
| 2023167 | Up to or equal to 2% | Less than 4 x 4 feet | C | No landing. Running slope 10%. Debris. | No |
| 2023168 | <Null> | <Null> | D | No PAR barricade | No |
| 2023169 | <Null> | <Null> | D | No PAR barricade | No |
| 2023170 | Up to or equal to 2% | Less than 4 x 4 feet | C | No landing | No |
| 2023171 | More than 2% | Less than 4 x 4 feet | C | Cross slope 2.5%. No landing. | No |
| 2023172 | Up to or equal to 2% | 4 x 4 feet or greater | B | Running slope 9.3%. | No |
| 2023173 | Up to or equal to 2% | 4 x 4 feet or greater | B | Running slope 8.5% | No |
| 2023174 | Up to or equal to 2% | 4 x 4 feet or greater | B | Running slope 9% | No |
| 2023175 | More than 2% | 4 x 4 feet or greater | B | Running slope 9.5%. Cross slope 2.5%. Vegetation blocking landing. | No |
| 2023176 | Up to or equal to 2% | Less than 4 x 4 feet | C | No landing | No |
| 2023177 | Up to or equal to 2% | Less than 4 x 4 feet | C | No landing | No |
| 2023178 | More than 2% | Less than 4 x 4 feet | C | No Landing. Cross slope 5%. PAR running slope 8%. | No |
| 2023179 | Up to or equal to 2% | Less than 4 x 4 feet | C | No Landing | No |
| 2023180 | Up to or equal to 2% | Less than 4 x 4 feet | C | No Landing | No |
| 2023181 | Up to or equal to 2% | Less than 4 x 4 feet | C | No Landing | No |
| 2023182 | Up to or equal to 2% | Less than 4 x 4 feet | C | No Landing | No |
| 2023183 | Up to or equal to 2% | Less than 4 x 4 feet | C | No Landing. Running slope 8.8%. | No |
| 2023184 | Up to or equal to 2% | Less than 4 x 4 feet | C | No Landing | No |

City of Sultan
2023 ADA Access Plan GIS Curb Ramp Inventory

| TSI_Curb_Ramp_ID | Cross_Slope | Landing | Grade * | Notes | ADA_Compliance |
|------------------|----------------------|-----------------------|---------|---|----------------|
| 2023185 | Up to or equal to 2% | Less than 4 x 4 feet | C | No Landing. Running slope 12%. | No |
| 2023186 | Up to or equal to 2% | Less than 4 x 4 feet | C | No Landing | No |
| 2023187 | More than 2% | Less than 4 x 4 feet | C | No Landing. Cross slope 4%. | No |
| 2023188 | Up to or equal to 2% | 4 x 4 feet or greater | A | <Null> | Yes |
| 2023189 | Up to or equal to 2% | 4 x 4 feet or greater | A | Debris | Yes |
| 2023190 | Up to or equal to 2% | 4 x 4 feet or greater | A | Debris. | Yes |
| 2023191 | Up to or equal to 2% | 4 x 4 feet or greater | A | Debris. | Yes |
| 2023192 | More than 2% | 4 x 4 feet or greater | A | Cross slope 3.5%. Landing slopes downward in PAR | No |
| 2023193 | More than 2% | Less than 4 x 4 feet | C | No Landing. Running slope 12%. Cross slope 3.5%. | No |
| 2023194 | Up to or equal to 2% | Less than 4 x 4 feet | C | No Landing. Running slope 9.5%. | No |
| 2023195 | Up to or equal to 2% | Less than 4 x 4 feet | C | No Landing | No |
| 2023196 | <Null> | <Null> | D | No receiving ramp at marked crossing | No |
| 2023197 | Up to or equal to 2% | Less than 4 x 4 feet | C | No Landing. Running slope 9.3%. | No |
| 2023198 | Up to or equal to 2% | Less than 4 x 4 feet | C | No Landing. Running slope 9%. | No |
| 2023199 | Up to or equal to 2% | Less than 4 x 4 feet | C | No landing. Running slope 8.8%. | No |
| 2023200 | Up to or equal to 2% | 4 x 4 feet or greater | A | Landing slope 2%. Minor curb lip. | No |
| 2023201 | Up to or equal to 2% | 4 x 4 feet or greater | A | Minor curb lip | No |
| 2023202 | Up to or equal to 2% | Less than 4 x 4 feet | C | No Landing | No |
| 2023203 | Up to or equal to 2% | Less than 4 x 4 feet | C | No Landing | No |
| 2023204 | Up to or equal to 2% | 4 x 4 feet or greater | C | Running slope 10%. Curb lip. | No |
| 2023205 | Up to or equal to 2% | 4 x 4 feet or greater | C | Running slope 11%. Curb lip. Vegetation. | No |
| 2023206 | Up to or equal to 2% | Less than 4 x 4 feet | B | Running slope 12%. Curb lip. | No |
| 2023207 | Up to or equal to 2% | Less than 4 x 4 feet | C | Running slope 10.3%. Curb lip. | No |
| 2023208 | Up to or equal to 2% | Less than 4 x 4 feet | A | DWS within noncompliant Landing | Yes |
| 2023209 | Up to or equal to 2% | 4 x 4 feet or greater | A | <Null> | Yes |
| 2023210 | Up to or equal to 2% | Less than 4 x 4 feet | C | No landing. Running slope 12.5%. | No |
| 2023211 | Up to or equal to 2% | 4 x 4 feet or greater | B | Running slope 9%. Curb lip. | No |
| 2023212 | Up to or equal to 2% | 4 x 4 feet or greater | B | Curb lip. | No |
| 2023213 | Up to or equal to 2% | 4 x 4 feet or greater | A | <Null> | Yes |
| 2023214 | More than 2% | Less than 4 x 4 feet | C | No Landing. Cross slope 2.5%. Flare running slope 9%. | No |
| 2023215 | Up to or equal to 2% | Less than 4 x 4 feet | C | No Landing. Side flare slope 9%. | No |
| 2023216 | More than 2% | 4 x 4 feet or greater | B | Cross slope 4.3%. PAR cross slope 6.8%. | No |
| 2023217 | More than 2% | Less than 4 x 4 feet | C | No Landing. Minor curb lip. Side flare slope 11%. | No |
| 2023218 | Up to or equal to 2% | Less than 4 x 4 feet | C | No Landing. Crack forming in ramp. Minor curb lip. | No |
| 2023219 | More than 2% | Less than 4 x 4 feet | C | No Landing. Cross slope 3%. Flare running slope 12%. | No |
| 2023220 | Up to or equal to 2% | Less than 4 x 4 feet | C | No Landing. Ramp 32 inches wide. | No |
| 2023221 | Up to or equal to 2% | Less than 4 x 4 feet | C | No landing | No |
| 2023222 | Up to or equal to 2% | Less than 4 x 4 feet | C | No landing. Side flares slope 9.8%. Crack forming inside flare. Minor curb lip. | No |
| 2023223 | Up to or equal to 2% | 4 x 4 feet or greater | A | <Null> | Yes |
| 2023224 | Up to or equal to 2% | 4 x 4 feet or greater | A | <Null> | Yes |
| 2023225 | More than 2% | Less than 4 x 4 feet | C | No landing. Running slope 9% | No |
| 2023226 | Up to or equal to 2% | 4 x 4 feet or greater | A | Debris. | Yes |
| 2023227 | Up to or equal to 2% | 4 x 4 feet or greater | A | <Null> | Yes |
| 2023228 | Up to or equal to 2% | Less than 4 x 4 feet | C | Running slope 10%. No landing | No |
| 2023229 | Up to or equal to 2% | Less than 4 x 4 feet | C | No landing | No |
| 2023230 | Up to or equal to 2% | Less than 4 x 4 feet | C | No Landing. Running slope 10%. | No |

City of Sultan
2023 ADA Access Plan GIS Curb Ramp Inventory

| TSI_Curb_Ramp_ID | Cross_Slope | Landing | Grade * | Notes | ADA_Compliance |
|------------------|----------------------|-----------------------|---------|--|----------------|
| 2023231 | More than 2% | 4 x 4 feet or greater | A | PAR cross slope 2.5%. South east flare slope 11%. | No |
| 2023232 | Up to or equal to 2% | 4 x 4 feet or greater | A | <Null> | Yes |
| 2023233 | <Null> | <Null> | D | No receiving ramp at marked crossing | No |
| 2023234 | Up to or equal to 2% | Less than 4 x 4 feet | C | No Landing. Running slope 9%. | No |
| 2023235 | More than 2% | Less than 4 x 4 feet | C | No Landing. Running slope 9%. Cross slope 3%. | No |
| 2023236 | Up to or equal to 2% | 4 x 4 feet or greater | A | <Null> | Yes |
| 2023237 | More than 2% | Less than 4 x 4 feet | C | No Landing. Minor curb lip. Side flare slope 12%. Ramp cross slope 3%. | No |
| 2023238 | <Null> | <Null> | D | <Null> | No |
| 2023239 | <Null> | <Null> | D | <Null> | No |
| 2023240 | <Null> | <Null> | D | No receiving ramp at intersection | No |
| 2023241 | <Null> | <Null> | D | No receiving ramp at intersection | No |
| 2023242 | <Null> | <Null> | D | No receiving ramp at intersection | No |
| 2023243 | Up to or equal to 2% | 4 x 4 feet or greater | B | Running slope 8.7%. | No |
| 2023244 | <Null> | <Null> | D | No receiving ramp at marked crossing | No |
| 2023245 | <Null> | <Null> | D | No receiving ramp at intersection | No |
| 2023246 | Up to or equal to 2% | 4 x 4 feet or greater | B | Curb barrier on left | No |
| 2023247 | <Null> | <Null> | D | No ramp at marked crossing | No |
| 2023248 | <Null> | <Null> | D | No ramp at marked crossing | No |
| 2023249 | <Null> | <Null> | D | No ramp or PAR at marked crossing | No |
| 2023250 | <Null> | <Null> | D | No receiving ramp at intersection | No |
| 2023251 | Up to or equal to 2% | 4 x 4 feet or greater | A | <Null> | Yes |
| 2023252 | Up to or equal to 2% | 4 x 4 feet or greater | A | <Null> | Yes |
| 2023253 | Up to or equal to 2% | 4 x 4 feet or greater | A | Running slope 9%. PAR cross slope %. Monitor sidewalk gap and adjacent vegetation. | No |
| 2023254 | Up to or equal to 2% | 4 x 4 feet or greater | A | <Null> | Yes |
| 2023255 | Up to or equal to 2% | 4 x 4 feet or greater | A | <Null> | Yes |
| 2023256 | Up to or equal to 2% | 4 x 4 feet or greater | A | <Null> | Yes |
| 2023257 | Up to or equal to 2% | 4 x 4 feet or greater | A | <Null> | Yes |
| 2023258 | Up to or equal to 2% | 4 x 4 feet or greater | A | <Null> | Yes |
| 2023259 | Up to or equal to 2% | 4 x 4 feet or greater | A | <Null> | Yes |
| 2023260 | Up to or equal to 2% | 4 x 4 feet or greater | A | <Null> | Yes |
| 2023261 | Up to or equal to 2% | 4 x 4 feet or greater | A | <Null> | Yes |
| 2023262 | Up to or equal to 2% | 4 x 4 feet or greater | A | <Null> | Yes |
| 2023263 | Up to or equal to 2% | 4 x 4 feet or greater | A | <Null> | Yes |
| 2023264 | Up to or equal to 2% | 4 x 4 feet or greater | A | <Null> | Yes |
| 2023265 | Up to or equal to 2% | 4 x 4 feet or greater | A | <Null> | Yes |
| 2023266 | Up to or equal to 2% | 4 x 4 feet or greater | A | <Null> | Yes |
| 2023267 | Up to or equal to 2% | 4 x 4 feet or greater | A | <Null> | Yes |
| 2023268 | Up to or equal to 2% | 4 x 4 feet or greater | A | <Null> | Yes |
| 2023269 | Up to or equal to 2% | 4 x 4 feet or greater | A | <Null> | Yes |
| 2023270 | <Null> | <Null> | D | No PAR barricade | No |
| 2023271 | More than 2% | Less than 4 x 4 feet | B | Running slope 9%. Cross slope 3%. PAR running slope 5%. | No |
| 2023272 | More than 2% | Less than 4 x 4 feet | B | Running slope 10%. Cross slope 10%. Landing PAR running slope 14%. | No |
| 2023273 | More than 2% | Less than 4 x 4 feet | B | Running slope 9%. Cross slope 4%. PAR running slope 5%. | No |
| 2023274 | <Null> | <Null> | D | No PAR barricade | No |
| 2023275 | <Null> | <Null> | D | No PAR barricade | No |

City of Sultan
2023 ADA Access Plan GIS Curb Ramp Inventory

| TSI_Curb_Ramp_ID | Cross_Slope | Landing | Grade * | Notes | ADA_Compliance |
|------------------|----------------------|-----------------------|---------|---|----------------|
| 2023276 | More than 2% | 4 x 4 feet or greater | B | Cross slope 3%. Matches roadway grade. PAR running slope 4%. | No |
| 2023277 | Up to or equal to 2% | 4 x 4 feet or greater | B | Running slope 10%. | No |
| 2023278 | More than 2% | 4 x 4 feet or greater | A | Running slope 8.7%. Cross slope 2.3% Matches roadway grade. Landing slopes within 3%. | Yes |
| 2023279 | More than 2% | 4 x 4 feet or greater | A | Cross slope 3%. Matches roadway grade. Landing slopes within 3.5% | Yes |
| 2023280 | <Null> | <Null> | D | No PAR barricade | No |
| 2023281 | Up to or equal to 2% | 4 x 4 feet or greater | A | <Null> | Yes |
| 2023282 | Up to or equal to 2% | 4 x 4 feet or greater | A | <Null> | Yes |
| 2023283 | Up to or equal to 2% | 4 x 4 feet or greater | A | <Null> | Yes |
| 2023284 | Up to or equal to 2% | 4 x 4 feet or greater | A | <Null> | Yes |
| 2023285 | <Null> | <Null> | C | No DWS transition to shoulder | No |
| 2023286 | Up to or equal to 2% | 4 x 4 feet or greater | A | <Null> | Yes |
| 2023287 | Up to or equal to 2% | 4 x 4 feet or greater | A | Debris. | Yes |
| 2023288 | Up to or equal to 2% | 4 x 4 feet or greater | A | <Null> | Yes |
| 2023289 | Up to or equal to 2% | 4 x 4 feet or greater | A | Monitor vegetation | Yes |
| 2023290 | Up to or equal to 2% | 4 x 4 feet or greater | A | Monitor gaps in adjacent PAR | Yes |
| 2023291 | Up to or equal to 2% | 4 x 4 feet or greater | A | <Null> | Yes |
| 2023292 | Up to or equal to 2% | 4 x 4 feet or greater | A | PAR cross slope 3%. Debris. | No |
| 2023293 | Up to or equal to 2% | 4 x 4 feet or greater | A | <Null> | Yes |
| 2023294 | <Null> | <Null> | D | No PAR barricade | No |
| 2023295 | More than 2% | 4 x 4 feet or greater | A | MEF required. Running slope 12%. Cross slope 5%. Matches roadway grade. PAR running slope 6%. PAR cross slope 3%. | No |
| 2023296 | More than 2% | 4 x 4 feet or greater | A | MEF required. Cross slope 10%. Matches roadway grade. Landing PAR running slope 11%. | No |
| 2023297 | More than 2% | 4 x 4 feet or greater | A | MEF required. Running slope 12%. Cross slope 11%. Landing PAR slope 14%. Landing cross slope 4%. | No |
| 2023298 | More than 2% | 4 x 4 feet or greater | A | MEF required. Cross slope 13%. Matches roadway grade. PAR running slope 12%. | No |
| 2023299 | <Null> | <Null> | D | No DWS PAR to shoulder transition | No |
| 2023300 | Up to or equal to 2% | 4 x 4 feet or greater | A | <Null> | Yes |
| 2023301 | Up to or equal to 2% | 4 x 4 feet or greater | A | <Null> | Yes |
| 2023302 | <Null> | <Null> | D | No DWS from PAR to shoulder transition | No |
| 2023303 | Up to or equal to 2% | Less than 4 x 4 feet | B | <Null> | No |
| 2023304 | Up to or equal to 2% | 4 x 4 feet or greater | A | <Null> | Yes |
| 2023305 | Up to or equal to 2% | 4 x 4 feet or greater | A | <Null> | Yes |
| 2023306 | Up to or equal to 2% | 4 x 4 feet or greater | B | Running slope 9%. PAR cross slope 2.7%. | No |
| 2023307 | Up to or equal to 2% | 4 x 4 feet or greater | A | <Null> | Yes |
| 2023308 | Up to or equal to 2% | 4 x 4 feet or greater | A | <Null> | Yes |
| 2023309 | <Null> | <Null> | D | No PAR barricade | No |
| 2023310 | <Null> | <Null> | D | <Null> | No |
| 2023311 | Up to or equal to 2% | 4 x 4 feet or greater | A | <Null> | Yes |
| 2023312 | More than 2% | 4 x 4 feet or greater | B | Cross slope 3%. Matches roadway grade. PAR cross slope 3%. | No |
| 2023313 | Up to or equal to 2% | 4 x 4 feet or greater | A | <Null> | Yes |
| 2023314 | <Null> | <Null> | D | No DWS at transition shoulder | No |
| 2023315 | <Null> | <Null> | D | No PAR barricade | No |
| 2023316 | <Null> | <Null> | D | No DWS at marked street | No |
| 2023317 | <Null> | <Null> | D | No DWS at marked street | No |

City of Sultan
2023 ADA Access Plan GIS Curb Ramp Inventory

| TSI_Curb_Ramp_ID | Cross_Slope | Landing | Grade * | Notes | ADA_Compliance |
|------------------|----------------------|-----------------------|---------|---|----------------|
| 2023318 | <Null> | <Null> | D | No DWS at marked street | No |
| 2023319 | <Null> | <Null> | D | No DWS at marked street | No |
| 2023320 | <Null> | <Null> | D | No DWS transition to roadway (marked street) | No |
| 2023321 | <Null> | <Null> | D | No DWS transition at end of PAR to shoulder | No |
| 2023322 | <Null> | <Null> | D | No DWS transition to shoulder at transit stop | No |
| 2023323 | Up to or equal to 2% | 4 x 4 feet or greater | A | <Null> | Yes |
| 2023324 | Up to or equal to 2% | 4 x 4 feet or greater | A | <Null> | Yes |
| 2023325 | Up to or equal to 2% | 4 x 4 feet or greater | A | Overgrown vegetation. | Yes |
| 2023326 | Up to or equal to 2% | 4 x 4 feet or greater | A | <Null> | Yes |
| 2023327 | Up to or equal to 2% | 4 x 4 feet or greater | B | PAR cross slope 6%. | No |
| 2023328 | <Null> | <Null> | D | No receiving ramp at intersection | No |
| 2023329 | Up to or equal to 2% | 4 x 4 feet or greater | A | Landing slopes within 2.5%. | No |
| 2023330 | <Null> | <Null> | D | No DWS transition to shoulder | No |
| 2023331 | <Null> | <Null> | D | No DWS transition to shoulder | No |
| 2023332 | <Null> | <Null> | D | Add DWS for consistency | No |
| 2023333 | <Null> | <Null> | D | No receiving DWS. Connects to paved shoulder. | No |
| 2023334 | Up to or equal to 2% | 4 x 4 feet or greater | A | <Null> | Yes |
| 2023335 | Up to or equal to 2% | 4 x 4 feet or greater | A | <Null> | Yes |
| 2023336 | Up to or equal to 2% | 4 x 4 feet or greater | A | DWS deterioration | No |
| 2023337 | Up to or equal to 2% | 4 x 4 feet or greater | A | DWS deterioration | No |
| 2023338 | Up to or equal to 2% | 4 x 4 feet or greater | A | <Null> | Yes |
| 2023339 | Up to or equal to 2% | 4 x 4 feet or greater | A | Monitor vegetation | Yes |
| 2023340 | Up to or equal to 2% | 4 x 4 feet or greater | A | DWS deterioration | No |
| 2023341 | Up to or equal to 2% | 4 x 4 feet or greater | A | <Null> | Yes |
| 2023342 | More than 2% | 4 x 4 feet or greater | A | Cross slope 3.3%. Matches road grade | Yes |
| 2023343 | More than 2% | 4 x 4 feet or greater | A | Cross slope 3.4%. Matches roadway grade. | Yes |
| 2023344 | More than 2% | 4 x 4 feet or greater | A | Cross slope 3.3%. Matches roadway grade. Monitor PAR crack | Yes |
| 2023345 | <Null> | <Null> | D | No DWS from PAR to shoulder transition | No |
| 2023346 | More than 2% | 4 x 4 feet or greater | A | Cross slope 4.5%. Matches roadway grade. | Yes |
| 2023347 | More than 2% | 4 x 4 feet or greater | A | Cross slope 8.1%. Matches roadway grade. PAR cross slope 3.6%. | No |
| 2023348 | <Null> | <Null> | D | No PAR barricade | No |
| 2023349 | <Null> | <Null> | D | No PAR barricade | No |
| 2023350 | <Null> | <Null> | D | No receiving ramp at intersection. | No |
| 2023351 | More than 2% | 4 x 4 feet or greater | A | Flare running slope 16%. Ramp cross slope 8.3%. Matches roadway grade. | Yes |
| 2023352 | Up to or equal to 2% | 4 x 4 feet or greater | A | Flare running slope 12.7%. Ramp cross slope 6%. Matches roadway grade. | Yes |
| 2023353 | <Null> | <Null> | D | No receiving ramp at intersection | No |
| 2023354 | More than 2% | 4 x 4 feet or greater | A | Cross slope 6.5%. Matches roadway grade | Yes |
| 2023355 | <Null> | <Null> | D | Missing transition to goat trail | No |
| 2023356 | <Null> | <Null> | D | Missing transition to goat trail | No |
| 2023357 | Up to or equal to 2% | 4 x 4 feet or greater | A | PAR cross slope 2.8% | No |
| 2023358 | Up to or equal to 2% | 4 x 4 feet or greater | A | PAR cross slope 2.7%. | No |
| 2023359 | More than 2% | Less than 4 x 4 feet | A | Running slope 9%. Cross slope 4.5%. Matches roadway grade. PAR running slope 6% | No |
| 2023360 | Up to or equal to 2% | 4 x 4 feet or greater | A | Monitor minor lip in front of DWS | Yes |
| 2023361 | More than 2% | Less than 4 x 4 feet | A | Running slope 9%. Cross slope 7%. Matches roadway grade. PAR running slope 10%. PAR cross slope 4.8%. | No |

City of Sultan
2023 ADA Access Plan GIS Curb Ramp Inventory

| TSI_Curb_Ramp_ID | Cross_Slope | Landing | Grade * | Notes | ADA_Compliance |
|------------------|----------------------|-----------------------|---------|---|----------------|
| 2023362 | More than 2% | 4 x 4 feet or greater | A | Cross slope 3.4%. Matches roadway grade. PAR running slope 4%. PAR cross slope 4.8%. Monitor panel gaps. | No |
| 2023363 | <Null> | <Null> | D | No receiving ramp across intersection | No |
| 2023364 | Up to or equal to 2% | 4 x 4 feet or greater | A | <Null> | Yes |
| 2023365 | Up to or equal to 2% | 4 x 4 feet or greater | A | <Null> | Yes |
| 2023366 | <Null> | <Null> | D | Missing PAR barricade or remove sidewalk extension. | No |
| 2023367 | Up to or equal to 2% | 4 x 4 feet or greater | A | <Null> | Yes |
| 2023368 | <Null> | <Null> | D | Missing PAR barricade or remove sidewalk extension. | No |
| 2023369 | Up to or equal to 2% | 4 x 4 feet or greater | A | <Null> | Yes |
| 2023370 | Up to or equal to 2% | 4 x 4 feet or greater | A | Running slope 9.3%. | No |
| 2023371 | Up to or equal to 2% | 4 x 4 feet or greater | A | <Null> | Yes |
| 2023372 | Up to or equal to 2% | 4 x 4 feet or greater | A | <Null> | Yes |
| 2023373 | Up to or equal to 2% | 4 x 4 feet or greater | A | <Null> | Yes |
| 2023374 | Up to or equal to 2% | 4 x 4 feet or greater | A | Monitor vegetation | Yes |
| 2023375 | Up to or equal to 2% | 4 x 4 feet or greater | A | Monitor vegetation | Yes |
| 2023376 | Up to or equal to 2% | 4 x 4 feet or greater | A | <Null> | Yes |
| 2023377 | Up to or equal to 2% | 4 x 4 feet or greater | A | Monitor front of DWS to curb debris | Yes |
| 2023378 | <Null> | <Null> | Other | PAR/sidewalk issue - Not ADA compliant | <Null> |
| 2023379 | <Null> | <Null> | Other | PAR/sidewalk issue. Not ADA compliant | <Null> |
| 2023380 | More than 2% | Less than 4 x 4 feet | A | Running slope 10%. Cross slope 5%. Matches roadway grade. PAR running slope 4%. PAR cross slope 2.6%. | No |
| 2023381 | Up to or equal to 2% | Less than 4 x 4 feet | A | Running slope 10%. Minor curb lip. Monitor DWS to curb gap. | No |
| 2023382 | <Null> | <Null> | D | No receiving ramp at intersection | No |
| 2023383 | Up to or equal to 2% | 4 x 4 feet or greater | A | Landing running slope 2.5%. | No |
| 2023384 | <Null> | <Null> | D | No PAR barricade. | No |
| 2023385 | <Null> | <Null> | D | No PAR barricade | No |
| 2023386 | Up to or equal to 2% | 4 x 4 feet or greater | A | Running slope 10%. Overgrown vegetation. | No |
| 2023387 | <Null> | <Null> | D | No receiving ramp at intersection | No |
| 2023388 | <Null> | <Null> | D | No PAR barricade. | No |
| 2023389 | <Null> | <Null> | D | No PAR barricade | No |
| 2023390 | Up to or equal to 2% | 4 x 4 feet or greater | A | <Null> | Yes |
| 2023391 | Up to or equal to 2% | 4 x 4 feet or greater | A | <Null> | Yes |
| 2023392 | Up to or equal to 2% | 4 x 4 feet or greater | A | Monitor panel gaps. | Yes |
| 2023393 | Up to or equal to 2% | 4 x 4 feet or greater | A | Landing slopes 3%. | No |
| 2023394 | Up to or equal to 2% | 4 x 4 feet or greater | B | 1 inch panel gap | No |
| 2023395 | <Null> | <Null> | D | No receiving ramp at intersection | No |
| 2023396 | Up to or equal to 2% | 4 x 4 feet or greater | A | Monitor panel gaps. | Yes |
| 2023397 | Up to or equal to 2% | 4 x 4 feet or greater | A | Monitor panel gaps | Yes |
| 2023398 | Up to or equal to 2% | 4 x 4 feet or greater | B | Crack in landing and adjacent PAR panels | No |
| 2023399 | <Null> | <Null> | D | DWS missing at end of PAR transition | No |
| 2023400 | <Null> | <Null> | D | No DWS at PAR transition to goat trail | No |
| 2023401 | <Null> | <Null> | Other | No DWS at 327th Court SE | <Null> |
| 2023402 | <Null> | <Null> | Other | No DWS at 327th Court SE | <Null> |
| 2023403 | <Null> | <Null> | Other | No DWS at 326th Court SE | <Null> |
| 2023404 | <Null> | <Null> | Other | No DWS at 326th Court SE | <Null> |
| 2023405 | Up to or equal to 2% | 4 x 4 feet or greater | A | <Null> | Yes |

City of Sultan
2023 ADA Access Plan GIS Curb Ramp Inventory

| TSI_Curb_Ramp_ID | Cross_Slope | Landing | Grade * | Notes | ADA_Compliance |
|------------------|----------------------|-----------------------|---------|------------------------------------|----------------|
| 2023406 | Up to or equal to 2% | 4 x 4 feet or greater | A | <Null> | Yes |
| 2023407 | Up to or equal to 2% | 4 x 4 feet or greater | A | <Null> | Yes |
| 2023408 | Up to or equal to 2% | 4 x 4 feet or greater | A | <Null> | Yes |
| 2023409 | Up to or equal to 2% | 4 x 4 feet or greater | A | <Null> | Yes |
| 2023410 | Up to or equal to 2% | 4 x 4 feet or greater | A | Air bubble under DWS in the middle | No |
| 2023411 | <Null> | <Null> | D | Missing PAR barricade | No |
| 2023412 | <Null> | <Null> | D | Missing PAR barricade | No |
| 2023413 | <Null> | <Null> | Other | No DWS at 133rd Place SE | <Null> |
| 2023414 | <Null> | <Null> | Other | No DWS at 133rd Place SE | <Null> |
| 2023415 | <Null> | <Null> | Other | No DWS at 132nd Place SE | <Null> |
| 2023416 | <Null> | <Null> | Other | No DWS at 132nd Place SE | <Null> |
| 2023417 | Up to or equal to 2% | 4 x 4 feet or greater | A | <Null> | Yes |
| 2023418 | Up to or equal to 2% | 4 x 4 feet or greater | A | <Null> | Yes |
| 2023419 | Up to or equal to 2% | 4 x 4 feet or greater | A | <Null> | Yes |
| 2023420 | Up to or equal to 2% | 4 x 4 feet or greater | A | <Null> | Yes |
| 2023421 | Up to or equal to 2% | 4 x 4 feet or greater | A | <Null> | Yes |
| 2023422 | Up to or equal to 2% | 4 x 4 feet or greater | A | <Null> | Yes |
| 2023423 | Up to or equal to 2% | 4 x 4 feet or greater | A | <Null> | Yes |
| 2023424 | Up to or equal to 2% | 4 x 4 feet or greater | A | <Null> | Yes |
| 2023425 | Up to or equal to 2% | 4 x 4 feet or greater | A | <Null> | Yes |
| 2023426 | Up to or equal to 2% | 4 x 4 feet or greater | A | <Null> | Yes |
| 2023427 | Up to or equal to 2% | 4 x 4 feet or greater | A | <Null> | Yes |
| 2023428 | Up to or equal to 2% | 4 x 4 feet or greater | A | <Null> | Yes |
| 2023429 | Up to or equal to 2% | 4 x 4 feet or greater | A | <Null> | Yes |
| 2023430 | Up to or equal to 2% | 4 x 4 feet or greater | A | <Null> | Yes |
| 2023431 | Up to or equal to 2% | 4 x 4 feet or greater | A | <Null> | Yes |
| 2023432 | Up to or equal to 2% | 4 x 4 feet or greater | A | <Null> | Yes |
| 2023433 | Up to or equal to 2% | 4 x 4 feet or greater | A | <Null> | Yes |
| 2023434 | Up to or equal to 2% | 4 x 4 feet or greater | A | <Null> | Yes |
| 2023435 | Up to or equal to 2% | 4 x 4 feet or greater | A | <Null> | Yes |
| 2023436 | Up to or equal to 2% | 4 x 4 feet or greater | A | <Null> | Yes |
| 2023437 | Up to or equal to 2% | 4 x 4 feet or greater | A | <Null> | Yes |
| 2023438 | Up to or equal to 2% | 4 x 4 feet or greater | A | <Null> | Yes |
| 2023439 | Up to or equal to 2% | 4 x 4 feet or greater | A | <Null> | Yes |
| 2023440 | Up to or equal to 2% | 4 x 4 feet or greater | A | <Null> | Yes |
| 2023441 | Up to or equal to 2% | 4 x 4 feet or greater | A | <Null> | Yes |
| 2023442 | Up to or equal to 2% | 4 x 4 feet or greater | A | <Null> | Yes |
| 2023443 | Up to or equal to 2% | 4 x 4 feet or greater | A | <Null> | Yes |
| 2023444 | Up to or equal to 2% | 4 x 4 feet or greater | A | <Null> | Yes |
| 2023445 | <Null> | <Null> | A | <Null> | Yes |
| 2023446 | <Null> | <Null> | A | <Null> | Yes |
| 2023447 | <Null> | <Null> | A | <Null> | Yes |
| 2023448 | <Null> | <Null> | A | <Null> | Yes |
| 2023449 | Up to or equal to 2% | 4 x 4 feet or greater | A | <Null> | Yes |
| 2023450 | Up to or equal to 2% | 4 x 4 feet or greater | A | <Null> | Yes |
| 2023451 | Up to or equal to 2% | 4 x 4 feet or greater | A | <Null> | Yes |

City of Sultan
2023 ADA Access Plan GIS Curb Ramp Inventory

| TSI_Curb_Ramp_ID | Cross_Slope | Landing | Grade * | Notes | ADA_Compliance |
|------------------|----------------------|-----------------------|---------|--|----------------|
| 2023452 | Up to or equal to 2% | 4 x 4 feet or greater | A | <Null> | Yes |
| 2023453 | Up to or equal to 2% | 4 x 4 feet or greater | A | <Null> | Yes |
| 2023454 | Up to or equal to 2% | 4 x 4 feet or greater | A | <Null> | Yes |
| 2023455 | Up to or equal to 2% | 4 x 4 feet or greater | A | <Null> | Yes |
| 2023456 | Up to or equal to 2% | 4 x 4 feet or greater | A | <Null> | Yes |
| 2023457 | Up to or equal to 2% | 4 x 4 feet or greater | A | <Null> | Yes |
| 2023458 | Up to or equal to 2% | 4 x 4 feet or greater | A | <Null> | Yes |
| 2023459 | Up to or equal to 2% | 4 x 4 feet or greater | A | <Null> | Yes |
| 2023460 | <Null> | <Null> | A | <Null> | Yes |
| 2023461 | Up to or equal to 2% | 4 x 4 feet or greater | A | <Null> | Yes |
| 2023462 | Up to or equal to 2% | 4 x 4 feet or greater | A | <Null> | Yes |
| 2023463 | Up to or equal to 2% | 4 x 4 feet or greater | A | Monitor debris | Yes |
| 2023464 | Up to or equal to 2% | 4 x 4 feet or greater | A | <Null> | Yes |
| 2023465 | Up to or equal to 2% | 4 x 4 feet or greater | A | <Null> | Yes |
| 2023466 | Up to or equal to 2% | 4 x 4 feet or greater | A | <Null> | Yes |
| 2023467 | Up to or equal to 2% | 4 x 4 feet or greater | A | Debris and Gravel. | Yes |
| 2023468 | Up to or equal to 2% | 4 x 4 feet or greater | A | <Null> | Yes |
| 2023469 | More than 2% | 4 x 4 feet or greater | A | Cross slope 3.4%. Matches roadway grade. | Yes |
| 2023470 | Up to or equal to 2% | 4 x 4 feet or greater | A | Monitor vegetation | Yes |
| 2023471 | More than 2% | Less than 4 x 4 feet | C | No DWS for transition to shoulder | No |
| 2023472 | Up to or equal to 2% | 4 x 4 feet or greater | A | Monitor vegetation. | Yes |
| 2023473 | More than 2% | 4 x 4 feet or greater | B | Flare running slope 9%. Flare cross slopes 3%. Monitor vegetation. | No |
| 2023474 | <Null> | <Null> | D | Abrupt pavement to gravel transition. | No |
| 2023475 | Up to or equal to 2% | 4 x 4 feet or greater | B | Landing slopes 3%. | No |
| 2023476 | Up to or equal to 2% | 4 x 4 feet or greater | B | <Null> | No |
| 2023477 | <Null> | <Null> | D | No receiving ramp at intersection | No |
| 2023478 | More than 2% | Less than 4 x 4 feet | B | Create WSDOT Driveway A option with PAR (sidewalk across private road/driveway). Running slope 10%. Cross slope 4%. Matches roadway grade. PAR cross slope 5%. | No |
| 2023479 | <Null> | <Null> | D | Create WSDOT Driveway A option with PAR (sidewalk across private road/driveway). | No |
| 2023480 | Up to or equal to 2% | 4 x 4 feet or greater | A | <Null> | Yes |
| 2023481 | Up to or equal to 2% | 4 x 4 feet or greater | A | <Null> | Yes |
| 2023482 | Up to or equal to 2% | 4 x 4 feet or greater | A | <Null> | Yes |
| 2023483 | Up to or equal to 2% | 4 x 4 feet or greater | A | <Null> | Yes |
| 2023484 | Up to or equal to 2% | 4 x 4 feet or greater | A | <Null> | Yes |
| 2023485 | Up to or equal to 2% | 4 x 4 feet or greater | A | <Null> | Yes |
| 2023486 | Up to or equal to 2% | 4 x 4 feet or greater | A | <Null> | Yes |
| 2023487 | <Null> | <Null> | D | No receiving ramp at intersection | No |
| 2023488 | Up to or equal to 2% | 4 x 4 feet or greater | A | <Null> | Yes |
| 2023489 | Up to or equal to 2% | 4 x 4 feet or greater | A | <Null> | Yes |
| 2023490 | Up to or equal to 2% | 4 x 4 feet or greater | A | <Null> | Yes |
| 2023491 | <Null> | <Null> | D | No receiving ramp at intersection | No |
| 2023492 | More than 2% | Less than 4 x 4 feet | C | No landing. Cross slope 3%. Steeper than roadway grade. | No |
| 2023493 | Up to or equal to 2% | Less than 4 x 4 feet | B | <Null> | No |
| 2023494 | More than 2% | Less than 4 x 4 feet | B | Running slope 9%. cross slope 3%. Matches roadway grade. | No |

City of Sultan
2023 ADA Access Plan GIS Curb Ramp Inventory

| TSI_Curb_Ramp_ID | Cross_Slope | Landing | Grade * | Notes | ADA_Compliance |
|------------------|----------------------|-----------------------|---------|---|----------------|
| 2023495 | Up to or equal to 2% | Less than 4 x 4 feet | B | Running slope 10%. | No |
| 2023496 | Up to or equal to 2% | 4 x 4 feet or greater | A | <Null> | Yes |
| 2023497 | Up to or equal to 2% | 4 x 4 feet or greater | A | <Null> | Yes |
| 2023498 | Up to or equal to 2% | 4 x 4 feet or greater | A | <Null> | Yes |
| 2023499 | Up to or equal to 2% | 4 x 4 feet or greater | A | <Null> | Yes |
| 2023500 | Up to or equal to 2% | 4 x 4 feet or greater | A | <Null> | Yes |
| 2023501 | Up to or equal to 2% | 4 x 4 feet or greater | A | Corner, curb, piece, broken | Yes |
| 2023502 | Up to or equal to 2% | 4 x 4 feet or greater | A | <Null> | Yes |
| 2023503 | Up to or equal to 2% | 4 x 4 feet or greater | A | <Null> | Yes |
| 2023504 | Up to or equal to 2% | Less than 4 x 4 feet | B | Monitor curb ramp panel upheaval | No |
| 2023505 | Up to or equal to 2% | Less than 4 x 4 feet | B | <Null> | No |
| 2023506 | Up to or equal to 2% | Less than 4 x 4 feet | C | Monitor overgrown vegetation. Monitor landing to PAR vertical discontinuity. | No |
| 2023507 | Up to or equal to 2% | Less than 4 x 4 feet | B | Running slope 13%. PAR cross slope 2.7%. | No |
| 2023508 | Up to or equal to 2% | 4 x 4 feet or greater | B | PAR cross slope 4% | No |
| 2023509 | Up to or equal to 2% | Less than 4 x 4 feet | B | Running slope 10%. PAR cross slope 2.7%. | No |
| 2023510 | Up to or equal to 2% | Less than 4 x 4 feet | B | Running slope 9%. Minor curb lip. | No |
| 2023511 | More than 2% | Less than 4 x 4 feet | B | Running slope 10%. Cross slope 4%. Matches roadway grade. PAR running slope 3.4%. PAR cross slope 2.7%. | No |
| 2023512 | More than 2% | Less than 4 x 4 feet | B | Running slope 10%. Cross slope 3%. Matches roadway grade. PAR running slope 3%. Monitor cracks. | No |
| 2023513 | <Null> | <Null> | D | No receiving ramp at intersection. | No |
| 2023514 | Up to or equal to 2% | Less than 4 x 4 feet | B | Minor curb lip. Running slope 9%. | No |
| 2023515 | Up to or equal to 2% | Less than 4 x 4 feet | B | Running slope 9.5%. Minor curb lip. | No |
| 2023516 | Up to or equal to 2% | Less than 4 x 4 feet | B | Running slope 9.5%. | No |
| 2023517 | More than 2% | Less than 4 x 4 feet | B | Minor curb lip. Running slope 10%. steeper than 4% roadway grade. Cross slope 5%. PAR running slope 6%. PAR cross slope 3%. | No |
| 2023518 | Up to or equal to 2% | 4 x 4 feet or greater | B | Running slope 10%. | No |
| 2023519 | Up to or equal to 2% | Less than 4 x 4 feet | B | Running slope 9.5%. Overgrown vegetation. Crack in flare. | No |
| 2023520 | Up to or equal to 2% | Less than 4 x 4 feet | C | Crack in ramp. Minor curb lip. Running slope 10%. | No |
| 2023521 | Up to or equal to 2% | 4 x 4 feet or greater | B | Running slope 8.8%. | No |
| 2023522 | Up to or equal to 2% | 4 x 4 feet or greater | A | Running slope 9%. | No |
| 2023523 | Up to or equal to 2% | 4 x 4 feet or greater | A | Running slope 9%. | No |
| 2023524 | More than 2% | 4 x 4 feet or greater | A | Running slope 10%. Cross slope 3%. Matches roadway grade. PAR running slope 3%. | No |
| 2023525 | Up to or equal to 2% | 4 x 4 feet or greater | A | <Null> | Yes |
| 2023526 | Up to or equal to 2% | 4 x 4 feet or greater | A | Running slope 9%. Debris. | No |
| 2023527 | Up to or equal to 2% | 4 x 4 feet or greater | A | Running slope 10%. | No |
| 2023528 | Up to or equal to 2% | Less than 4 x 4 feet | B | Running slope 9%. | No |
| 2023529 | Up to or equal to 2% | Less than 4 x 4 feet | B | Running slope 12%. PAR cross slope 2.7%. | No |
| 2023530 | Up to or equal to 2% | Less than 4 x 4 feet | B | Running slope 10%. Minor curb lip. | No |
| 2023531 | Up to or equal to 2% | Less than 4 x 4 feet | B | Running slope 10%. Minor curb lip. | No |
| 2023532 | Up to or equal to 2% | Less than 4 x 4 feet | C | No Landing. Running slope 8.7%. Curb lip. | No |
| 2023533 | Up to or equal to 2% | 4 x 4 feet or greater | A | <Null> | Yes |
| 2023534 | Up to or equal to 2% | Less than 4 x 4 feet | B | North slopes 2.7%. East slopes 3%. | No |
| 2023535 | Up to or equal to 2% | 4 x 4 feet or greater | B | Landing in PAR | No |
| 2023536 | Up to or equal to 2% | 4 x 4 feet or greater | A | Monitor vegetation | Yes |
| 2023537 | Up to or equal to 2% | 4 x 4 feet or greater | A | <Null> | Yes |

City of Sultan
2023 ADA Access Plan GIS Curb Ramp Inventory

| TSI_Curb_Ramp_ID | Cross_Slope | Landing | Grade * | Notes | ADA_Compliance |
|------------------|----------------------|-----------------------|---------|--|----------------|
| 2023538 | Up to or equal to 2% | 4 x 4 feet or greater | A | <Null> | Yes |
| 2023539 | Up to or equal to 2% | 4 x 4 feet or greater | A | <Null> | Yes |
| 2023540 | More than 2% | 4 x 4 feet or greater | C | No transition to cul-de-sac. Cross slope 3%. | No |
| 2023541 | More than 2% | Less than 4 x 4 feet | C | No transition to cul-de-sac. Cross slope 3%. | No |
| 2023542 | Up to or equal to 2% | 4 x 4 feet or greater | C | No DWS transition to gravel and roadway | No |
| 2023543 | Up to or equal to 2% | 4 x 4 feet or greater | C | No DWS transition to gravel and road | No |
| 2023544 | <Null> | <Null> | D | No ramp to gravel and road | No |
| 2023545 | <Null> | <Null> | D | No receiving ramp at intersection. | No |
| 2023546 | <Null> | <Null> | D | No receiving ramp at intersection. | No |
| 2023547 | <Null> | <Null> | D | No DWS at end of PAR transition to street | No |
| 2023548 | More than 2% | 4 x 4 feet or greater | C | No DWS transition to gravel and roadway | No |
| 2023549 | Up to or equal to 2% | 4 x 4 feet or greater | B | Running slope 9.5%. Landing slopes 2.5%. Debris. | No |
| 2023550 | Up to or equal to 2% | 4 x 4 feet or greater | B | PAR cross slope 2.7%. | No |
| 2023551 | <Null> | <Null> | D | No receiving ramp at intersection | No |
| 2023552 | <Null> | <Null> | C | No DWS transition to roadway | No |
| 2023553 | <Null> | <Null> | C | No DWS transition to roadway | No |
| 2023554 | <Null> | <Null> | D | No DWS transition to gravel - or pave PAR across gravel. | No |
| 2023555 | <Null> | <Null> | D | No DWS transition to gravel - or pave PAR across gravel. | No |
| 2023556 | Up to or equal to 2% | 4 x 4 feet or greater | B | DWS deterioration. Curb lip. | No |
| 2023557 | Up to or equal to 2% | Less than 4 x 4 feet | B | DWS deterioration. Debris and vegetation in landing area and at curb. | No |
| 2023558 | <Null> | <Null> | D | No receiving ramp at intersection. | No |
| 2023559 | Up to or equal to 2% | 4 x 4 feet or greater | A | <Null> | Yes |
| 2023560 | Up to or equal to 2% | 4 x 4 feet or greater | A | <Null> | Yes |
| 2023561 | Up to or equal to 2% | 4 x 4 feet or greater | A | <Null> | Yes |
| 2023562 | Up to or equal to 2% | 4 x 4 feet or greater | A | <Null> | Yes |
| 2023563 | Up to or equal to 2% | 4 x 4 feet or greater | A | <Null> | Yes |
| 2023564 | Up to or equal to 2% | Less than 4 x 4 feet | C | Running slope 10%. No landing. | No |
| 2023565 | Up to or equal to 2% | 4 x 4 feet or greater | A | <Null> | Yes |
| 2023566 | Up to or equal to 2% | 4 x 4 feet or greater | A | <Null> | Yes |
| 2023567 | <Null> | <Null> | Other | NO DWS at 14th Ave | <Null> |
| 2023568 | <Null> | <Null> | Other | No DWS at Wyndham Place | <Null> |
| 2023569 | Up to or equal to 2% | 4 x 4 feet or greater | D | No DWS. Steep slope at curb. | No |
| 2023570 | <Null> | <Null> | D | Missing PAR barricade. | No |
| 2023571 | <Null> | <Null> | D | No receiving ramp. Driveway. Is this a non-compliance issue?. | No |
| 2023572 | <Null> | <Null> | D | No receiving ramp at intersection. Is this a non-compliance issue with driveway? | No |
| 2023573 | <Null> | <Null> | D | No receiving ramp at intersection. Is this a non-compliance issue with driveway? | No |
| 2023574 | <Null> | <Null> | D | No receiving ramp at intersection. Is this a non-compliance issue at driveway? | No |
| 2023575 | <Null> | <Null> | D | No PAR barricade. | No |
| 2023576 | <Null> | <Null> | D | No PAR barricade. | No |
| 2023577 | <Null> | <Null> | D | No PAR barricade | No |
| 2023578 | <Null> | <Null> | D | No PAR barricade | No |
| 2023579 | <Null> | <Null> | Other | No DWS at Cheryl Way | <Null> |
| 2023580 | <Null> | <Null> | D | No PAR barricade | No |
| 2023581 | <Null> | <Null> | D | No receiving ramp at intersection. | No |
| 2023582 | <Null> | <Null> | D | No receiving ramp at intersection. | No |
| 2023583 | <Null> | <Null> | D | No PAR barricade. This is not a crossing. Ramp not required. | No |

City of Sultan
2023 ADA Access Plan GIS Curb Ramp Inventory

| TSI_Curb_Ramp_ID | Cross_Slope | Landing | Grade * | Notes | ADA_Compliance |
|------------------|----------------------|-----------------------|---------|---|----------------|
| 2023584 | <Null> | <Null> | D | No PAR barricade | No |
| 2023585 | <Null> | <Null> | Other | No DWS at Woodwind Palce | No |
| 2023586 | <Null> | <Null> | D | Provide blended transition to street | No |
| 2023587 | Up to or equal to 2% | 4 x 4 feet or greater | A | <Null> | Yes |
| 2023588 | More than 2% | 4 x 4 feet or greater | B | Cross slope 3%. Steeper than 2.4% roadway grade. PAR running slope 2.4%. | No |
| 2023589 | Up to or equal to 2% | 4 x 4 feet or greater | B | Running slope 10%. PAR cross slope 4%. | No |
| 2023590 | Up to or equal to 2% | Less than 4 x 4 feet | C | Cross slope 9%. PAR cross slope 4%. Curb lip. DWS deterioration. | No |
| 2023591 | More than 2% | 4 x 4 feet or greater | C | Running slope 22%. Cross slope 4%. No DWS transition to shoulder | No |
| 2023592 | More than 2% | Less than 4 x 4 feet | C | Running slope 10%. Cross slope 2.6%. PAR cross slope 3%. Curb lip. Pavement asphalt upheaval in crossing. | No |
| 2023593 | Up to or equal to 2% | 4 x 4 feet or greater | B | PAR cross slope 3%. DWS deterioration. | No |
| 2023594 | Up to or equal to 2% | Less than 4 x 4 feet | B | Running slope 10%. PAR cross slope 2.5%. | No |
| 2023595 | Up to or equal to 2% | 4 x 4 feet or greater | A | <Null> | Yes |